

TERMO DE ACEITE TÉCNICO

Solicitante: VIVO- Projeto Escolas Rurais

Cliente: VIVO NOC/Operador: Rogério Momi Frias

> **Empresa** VSAT-ID Link kbps Plataforma **EMC** Brasil 256/128 **VSAT** VIVO-PER-26078538-PE



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

9.320000 12.055825 DVB-S2 102 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up : 1326, T14R Beam Network Frequency : 12.055683 GHz

: 9.320125 Msps

Symbol Rate S2 ModCod

> - receiving : 15 8PSK-5/6 - current max : 16 8PSK-8/9

Pilot : On Frame length

: Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 14.8 dB Input Power : -31 dBm

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -30 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 35.0 dBm

EIRP : 48.0 dBW

Default CW Frequency: 14.125750 GHz

ATM mode : VC-Mux Header Compression : None

Satellite (DVB) Transmitter Status

State : On (DVB-RCS)
IDU Output Power : -19.0 dBm
ODU Output Power : 35.5 dBm

EIRP : 48.0 dBW Es/No : 13.5 dB

Header Compression: Disabled Timing correction: -167 us (262177 us)

Frequency correction: -430 Hz

```
Resporta de 8.8.8.8: bytes=32 tenpo-60me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-744me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-744me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-79me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-716me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-79me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-716me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-779me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-579me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-579me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-579me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-775me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-578me TIL-53
Resporta de 8.8.8.8: bytes=32 tenpo-578m
```