



TERMO DE ACEITE TÉCNICO





dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176280 GHz Symbol Rate : 4.883051 Msps

S2 ModCod

- receiving : 4 QPSK-1/2

- current max : 21 16APSK-5/6

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 16.8 dB Input Power : -33 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled

IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max

EIRP : max

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -13.3 dBm
ODU Output Power : 35.0 dBm

EIRP : 48.3 dBW Es/No : 15.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -390 us (281145 us)

Frequency correction: 150 Hz

arp show

NetAddr State MacAddr If 10.212.225.2 Dynamic b4:99:ba:00:92:6b 1

device show

System Information:

Name : SEE-MAGA-22172 Location : MANGA - MG

Contact:

System Up time : 0 days, 00:23:34

CPU Load : 15%

System time(UTC) : 24 October 2017 17:22:23

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:57:e9 Satellite (DVB) : 00:20:0e:10:57:e9

Pinging 10.212.225.1 with 32 bytes of data:

```
Reply from 10.212.225.1: bytes=32 time=507ms TTL=56 Reply from 10.212.225.1: bytes=32 time=545ms TTL=56 Reply from 10.212.225.1: bytes=32 time=559ms TTL=56 Reply from 10.212.225.1: bytes=32 time=513ms TTL=56 Reply from 10.212.225.1: bytes=32 time=551ms TTL=56 Reply from 10.212.225.1: bytes=32 time=546ms TTL=56 Reply from 10.212.225.1: bytes=32 time=546ms TTL=56 Reply from 10.212.225.1: bytes=32 time=526ms TTL=56 Reply from 10.212.225.1: bytes=32 time=511ms TTL=56 Reply from 10.212.225.1: bytes=32 time=555ms TTL=56 Reply from 10.212.225.1: bytes=32 time=555ms TTL=56
```

Ping statistics for 10.212.225.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds:

Minimum = 507ms, Maximum = 559ms, Average = 525ms

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Dalva Lopo da Silva
Cargo	Diretora
Identidade	10141901-1
Telefone	38-9-9939-8827