


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan Junior

GRE/Prodemge: João Antinossi Responsável/cliente: MARILUCI SOARES CONDENSSA

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-ITRA-23784 2Mbps VSAT



Satellite (DVB) RX Configuration _____ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

8.883000 * 0 0 12.176420 DVB-S2 104 0 0.0 E

Yes

0 0.0 E 1 1 1.333333 12.173500 DVB-S2 104

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65281, Prodei : 12.176423 GHz Frequency Symbol Rate : 8.882982 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

: On Pilot Frame length : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 15.9 dB SNR : -40 dBm Input Power

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -18.2 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -191 us (266647 us)
Frequency correction: 130 Hz
System Information:
    Name
                        : SEE-ITRA-23784
    Location
                         : ITABIRA - MG
    Contact
    System Up time : 0 days, 00:15:33
CPU Load : 14%
System time(UTC) : 18 January 2018 20:49:43
Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
                         : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:94:70
Satellite (DVB) : 00:20:0e:10:94:70
NetAddr
           State MacAddr
    10.215.76.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.215.76.1 with 32 bytes of data:
Reply from 10.215.76.1: bytes=32 time=540ms TTL=56
Reply from 10.215.76.1: bytes=32 time=560ms TTL=56
Reply from 10.215.76.1: bytes=32 time=546ms TTL=56
Reply from 10.215.76.1: bytes=32 time=581ms TTL=56
Reply from 10.215.76.1: bytes=32 time=541ms TTL=56
Reply from 10.215.76.1: bytes=32 time=563ms TTL=56
Reply from 10.215.76.1: bytes=32 time=548ms TTL=56
Reply from 10.215.76.1: bytes=32 time=541ms TTL=56
Reply from 10.215.76.1: bytes=32 time=528ms TTL=56
Reply from 10.215.76.1: bytes=32 time=563ms TTL=56
Ping statistics for 10.215.76.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
```

Minimum = 528ms, Maximum = 581ms, Average = 551ms

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br – ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: MARILUCI SOARES CONDENSSA Função: DIRETORA MASP: 894727-7 Telefone: (31) 3839-8038 Horário: 07:00 as 18:00