


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: João Carlos

GRE/Prodemge: João Antinossi Responsável/cliente: Telma Argemira Campos Moreira

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-ITBA-22035 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 17/10/2017 12:38:19

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 * 0 0 4.883300 0 0.0 E

Yes

1 1 0 0.0 E 16.667000 11.962753 DVB-S2 2

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176366 GHz Frequency Symbol Rate : 4.882960 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 17.3 dB Input Power : -33 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -17.5 dBm
ODU Output Power : 33.5 dBm
EIRP
                     : 46.5 dBW
Es/No
                     : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -365 us (281361 us)
Frequency correction: 50 Hz
System Information:
            : SEE-ITBA-22035
    Name
    Location
                         : ITAMARANDIBA
    Contact
    System Up time : 0 days, 00:08:06
CPU Load : 6%
System time(UTC) : 17 October 2017 11:40:06
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5f:f0 Satellite (DVB) : 00:20:0e:10:5f:f0
NetAddr
             State MacAddr
   10.212.107.2 Dynamic 54:04:a6:8e:d3:f6 1
Pinging 10.212.107.1 with 32 bytes of data:
Reply from 10.212.107.1: bytes=32 time=581ms TTL=56
Reply from 10.212.107.1: bytes=32 time=579ms TTL=56
Reply from 10.212.107.1: bytes=32 time=568ms TTL=56
Reply from 10.212.107.1: bytes=32 time=562ms TTL=56
Reply from 10.212.107.1: bytes=32 time=570ms TTL=56
Reply from 10.212.107.1: bytes=32 time=559ms TTL=56
Reply from 10.212.107.1: bytes=32 time=562ms TTL=56
Reply from 10.212.107.1: bytes=32 time=669ms TTL=56
Reply from 10.212.107.1: bytes=32 time=581ms TTL=56
Reply from 10.212.107.1: bytes=32 time=588ms TTL=56
Ping statistics for 10.212.107.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 559ms, Maximum = 669ms, Average = 581ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: Telma Argemira Campos Moreira Função: Diretora Identidade: MASP 322159-5
Horário de funcionamento – 07hrs às 22:30hrs