

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Ermínio Junior


Operadora/Cliente Joao Gustavo

Responsável/cliente Wilson Fernades

Consórcio
EMC/Vodanet

VSAT-ID
SEE-SAAS-22790
Porta kbps
Plataforma
VSAT





SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57 # dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -20.2 dBm

Es/No : 14.0 dB

Header Compression : Disabled - HC for RCS2 not supported by HUB

Timing correction : -334 us (280654 us)

Frequency correction: 150 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

```
Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName
* 0 0 4.883300
                   12.176420 DVB-S2 104
                                             0.00E
 1 1 16.667000
                   11.962753 DVB-S2 2
                                            0.0E
Satellite (DVB) Receiver Status
Rx State
              : On
DVB State
               : Forward link up
               : 65281,\ Prodemge@Vodanet
Network
Frequency
               : 12.176496 GHz
Symbol Rate
                : 4.883045 Msps
S2 ModCod
   - receiving : 21 16APSK-5/6
   - current max : 21 16APSK-5/6
Pilot
            : On
Frame length
                : Short
DVB S2 Mode
                  : ACM
DVB S2 Stream type: MPEG-TS
Roll off
             : 0.20
SNR
             : 16.7 dB
Input Power
               : -40 dBm
# arp show
 NetAddr
             State
                     MacAddr
10.214.104.1 Dynamic 00200E105212 1
# device show
System Information:
  Name
                : SEE-SAAS-22790
  Location
                : SALINAS
  Contact
                   : 0 days, 00:35:54
  System Up time
                  : 13%
  CPU Load
  System time(UTC) : 17 November 2017 14:52:06
  Broadcast Message : not set
HW:
  Model
                : SatLink 2000
  HW ID
                 : 120033
  Main board ID
                  : 120026 R6.2
MAC addresses:
  Ethernet (LAN)
                   : 00:20:0e:10:52:12
  Satellite (DVB)
                  : 00:20:0e:10:52:12
#
Pinging 10.214.104.1 with 32 bytes of data:
Reply from 10.214.104.1: bytes=32 time=601ms TTL=56
Reply from 10.214.104.1: bytes=32 time=538ms TTL=56
Reply from 10.214.104.1: bytes=32 time=537ms TTL=56
Reply from 10.214.104.1: bytes=32 time=529ms TTL=56
Reply from 10.214.104.1: bytes=32 time=566ms TTL=56
Reply from 10.214.104.1: bytes=32 time=569ms TTL=56
Reply from 10.214.104.1: bytes=32 time=543ms TTL=56
Reply from 10.214.104.1: bytes=32 time=556ms TTL=56
Reply from 10.214.104.1: bytes=32 time=552ms TTL=56
Reply from 10.214.104.1: bytes=32 time=526ms TTL=56
Ping statistics for 10.214.104.1:
  Packets: Sent = 10, Received = 10, Lost = 0 (0\% loss),
Approximate round trip times in milli-seconds:
  Minimum = 526ms, Maximum = 601ms, Average = 551ms
www.yahoo.com.br
```

Enable

Name

Yes

Yes

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Wilson Fernandes
Cargo	Diretor
Identidade	619840-2
Telefone	038-9-9948-2835
Funcionamento	07:00-17:15
Onde ficou	Computador da diretoria