

## **TERMO DE ACEITE TÉCNICO**

Solicitante: CREDISIS

NOC/Operador: Alexandre Cruz


Cliente: CREDISIS

Empresa
EMC Brasil

VSAT-ID
CREDISIS-MINISTRO-RO

Link kbps
1M/512k

Plataforma VSAT



## # device show

## System Information:

Name : CREDISIS-MINISTRO-RO

Location : MINISTRO - RO

Contact :

System Up time : 0 days, 01:14:14

CPU Load : 12%

System time(UTC) : 03 March 2017 17:16:17

Broadcast Message : not set

## HW:

Model : SatLink 2000

HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:8f:47

Satellite (DVB) : 00:20:0e:10:8f:47

# dvb rx show

Satellite (DVB) RX Configuration

\_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

\* 0 0 9.320000 12.055825 DVB-S2 102 0 0.0 E Yes

Satellite (DVB) Receiver Status

-----

Rx State : On

DVB State : Forward link up

Network : 1326, T14R Beam

Frequency: 12.055830 GHz

Symbol Rate : 9.320116 Msps

S2 ModCod

- receiving : 12 8PSK-3/5

- current max : 15 8PSK-5/6

Pilot : On

Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20

Input Power : -41 dBm
# dvb tx show
Satellite (DVB) TX Configuration
Auto start : Enabled
IDU Output Power : -13 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression: None
Satellite (DVB) Transmitter Status
State : On (DVB-RCS)
IDU Output Power : -13.1 dBm
Es/No : 12.0 dB
Header Compression: Disabled
Timing correction : -138 us (257369 us)
Frequency correction: -10 Hz
# dvb cr show
Capacity parameters per channel:
Channel CRA[kbps] Allocated[kbps]
0 0 0
Requested capacity per QoS class:
Channel CRClass MaxRBDC[kbps] MaxVBDC[kB] RateReq[kbps] VolReq[octs] Description

SNR : 12.2 dB

0	0	612	61	2	0 Best Effort	
0	1	0	0	0	0 VoiP	
0	2	0	0	0	0 ViC	
0	3	32	3	0	0 Critical Data	

RBDC timeout 5 VBDC timeout 20

VBDC computation interval 200 ms (configured 0)

#