

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Joao Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Doraci Souza Correira

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SATO-231322MbpsVSAT





Satellite (DVB) RX Configuration
----Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

1 1

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176400 GHz Symbol Rate : 8.883044 Msps

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 15.7 dB
Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -19 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -19.1 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -213 us (264648 us)
Frequency correction: 120 Hz
System Information:
   Name
                        : SEE-SATO-23132
    Location
                         : SANTA MARIA DO SALTO - MG
    Contact
    System Up time : 0 days, 00:33:42 CPU Load : 29%
    System time(UTC) : 12 December 2017 18:22:58 Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
                        : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:57:b8
Satellite (DVB) : 00:20:0e:10:57:b8
NetAddr
           State MacAddr
    10.214.51.2 Dynamic b4:99:ba:00:92:6b 1
Pinging 10.214.51.1 with 32 bytes of data:
Reply from 10.214.51.1: bytes=32 time=554ms TTL=56
Reply from 10.214.51.1: bytes=32 time=752ms TTL=56
Reply from 10.214.51.1: bytes=32 time=616ms TTL=56
Reply from 10.214.51.1: bytes=32 time=537ms TTL=56
Reply from 10.214.51.1: bytes=32 time=585ms TTL=56
Reply from 10.214.51.1: bytes=32 time=538ms TTL=56
Reply from 10.214.51.1: bytes=32 time=596ms TTL=56
Reply from 10.214.51.1: bytes=32 time=624ms TTL=56
Reply from 10.214.51.1: bytes=32 time=525ms TTL=56
Reply from 10.214.51.1: bytes=32 time=625ms TTL=56
Ping statistics for 10.214.51.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 752ms, Average = 595ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Doraci Souza Correira Função: Diretora MASP: 640341-4 Telefone: 33-987503931 Funcionamento: 18:00h às 22:15h