

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Elizângela Pedroso Lopes

> Porta kbps Plataforma Consórcio **VSAT-ID VSAT** EMC/Vodanet SEE-JEAS-22781 2Mbps





Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State

Network

: Forward link up : 65281, Prodemge@Vodanet : 12.176397 GHz : 4.882974 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor
DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.0 dB SNR Input Power : -33 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -17.8 dBm
ODU Output Power : 32.9 dBm
EIRP
                    : 46.2 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -337 us (280830 us)
Frequency correction: 50 Hz
System Information:
                        : SEE-JEAS-22781
    Name
    Location
                        : Jenipapo de Minas - MG
    Contact
    System Up time : 0 days, 00:02:46 CPU Load : 13%
    System time(UTC) : 20 November 2017 14:44:47
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:49:bd Satellite (DVB) : 00:20:0e:10:49:bd
    Ethernet (LAN)
NetAddr
           State MacAddr
    10.214.91.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.214.91.1 with 32 bytes of data:
Reply from 10.214.91.1: bytes=32 time=593ms TTL=56
Reply from 10.214.91.1: bytes=32 time=667ms TTL=56
Reply from 10.214.91.1: bytes=32 time=556ms TTL=56
Reply from 10.214.91.1: bytes=32 time=627ms TTL=56
Reply from 10.214.91.1: bytes=32 time=541ms TTL=56
Reply from 10.214.91.1: bytes=32 time=642ms TTL=56
Reply from 10.214.91.1: bytes=32 time=541ms TTL=56
Reply from 10.214.91.1: bytes=32 time=531ms TTL=56
Reply from 10.214.91.1: bytes=32 time=643ms TTL=56
Reply from 10.214.91.1: bytes=32 time=526ms TTL=56
Ping statistics for 10.214.91.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 526ms, Maximum = 667ms, Average = 586ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Elizângela Pedroso Lopes
Função: Vice-Diretora
MASP: 123.1855-6
Telefone: 33-9886-9403
Telefolic. 33 70000 7403
Funcionamento: 07:00 às 18:30h