



# TERMO DE ACEITE TÉCNICO

Name

Solicitante: PRODEMGE / SEE NOC/Operadora: Ermínio Junior Operadora/Cliente Ronaldo Candido Responsável/cliente Valdomiro Cardoso GRE/Prodemge: João Antinossi Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-RIAS-22567 2Mbps **VSAT** 





# dvb rx show

### Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

 $Idx\ Pri\ SymbRate[Msps]\ Freq[GHz]\ Mode\ PopId\ SatId\ Pos\ SatName$ 

Enable

4.883300 12.176420 DVB-S2 104 0.0EYes 1 1 16.667000 11.962753 DVB-S2 2 0.0EYes

Satellite (DVB) Receiver Status

Rx State : On

**DVB** State : Forward link up

: 65281, Prodemge@Vodanet Network

Frequency : 12.176462 GHz Symbol Rate : 4.882990 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short : ACM DVB S2 Mode DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 16.3 dB Input Power : -32 dBm

### # dvb tx show Satellite (DVB) TX Configuration Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm : 46.5 dBW Default CW Frequency: 0.000000 GHz ATM mode : VC-Mux Header Compression: UDP/IP Satellite (DVB) Transmitter Status : On (DVB-RCS2) State IDU Output Power : -17.7 dBm ODU Output Power : 33.0 dBm : 46.3 dBW Es/No : 13.0 dB Header Compression: Disabled - HC for RCS2 not supported by HUB Timing correction : -194 us (280642 us) Frequency correction: 140 Hz # arp show NetAddr State MacAddr 10.213.150.2 Dynamic 80:ee:73:a4:e2:ba 1 # device show **System Information:** : SEE-RIAS-22567 Name Location : RIO PARDO DE MINAS - MG Contact System Up time : 0 days, 00:07:12 : 13% CPU Load System time(UTC) : 10 November 2017 20:48:35 Broadcast Message : not set HW: Model : SatLink 2000 : 120033 HW ID Main board ID : 120026 R6.2 MAC addresses: Ethernet (LAN) : 00:20:0e:10:5b:c3 Satellite (DVB) : 00:20:0e:10:5b:c3 Pinging 10.213.150.1 with 32 bytes of data: Reply from 10.213.150.1: bytes=32 time=539ms TTL=56 Reply from 10.213.150.1: bytes=32 time=542ms TTL=56 Reply from 10.213.150.1: bytes=32 time=568ms TTL=56 Reply from 10.213.150.1: bytes=32 time=564ms TTL=56 Reply from 10.213.150.1: bytes=32 time=550ms TTL=56 Reply from 10.213.150.1: bytes=32 time=538ms TTL=56 Reply from 10.213.150.1: bytes=32 time=543ms TTL=56 Reply from 10.213.150.1: bytes=32 time=517ms TTL=56 Reply from 10.213.150.1: bytes=32 time=517ms TTL=56 Reply from 10.213.150.1: bytes=32 time=565ms TTL=56 Ping statistics for 10.213.150.1: Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds:

#### www.yahoo.com.br

Minimum = 517ms, Maximum = 568ms, Average = 574ms

www.hotmail.com

www.google.com

## www.prodemge.gov.br

Responsável	Valdomiro Cardoso
Cargo	Diretor
Identidade	1188315-4
Telefone	038-9-9139-1429//038-9-9139-
	1439
Funcionamento	06: 00 às 11:30