

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Rogerio Esteves Nunes

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-NORO-229472MbpsVSAT





Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up
Network : 65281, Prodemge@Vodanet

Network : 65281, Proder Frequency : 12.176538 GHz Symbol Rate : 4.883009 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20

SNR : 14.9 dB

Input Power : -37 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -19.2 dBm

ODU Output Power : 33.2 dBm

EIRP
______
Es/No
                    : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -344 us (280802 us)
Frequency correction: 10 Hz
System Information:
    Name
                       : SEE-NORO-22947
    Location
                        : Novo Cruzeiro - MG
    Contact
    System Up time : 0 days, 00:08:16 CPU Load : 16%
    System time(UTC) : 21 November 2017 12:24:47
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:54:7d
Satellite (DVB) : 00:20:0e:10:54:7d
    Ethernet (LAN)
NetAddr
             State MacAddr
   10.215.140.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.215.140.1 with 32 bytes of data:
Reply from 10.215.140.1: bytes=32 time=563ms TTL=56
Reply from 10.215.140.1: bytes=32 time=542ms TTL=56
Reply from 10.215.140.1: bytes=32 time=535ms TTL=56
Reply from 10.215.140.1: bytes=32 time=572ms TTL=56
Reply from 10.215.140.1: bytes=32 time=567ms TTL=56
Reply from 10.215.140.1: bytes=32 time=634ms TTL=56
Reply from 10.215.140.1: bytes=32 time=593ms TTL=56
Reply from 10.215.140.1: bytes=32 time=858ms TTL=56
Reply from 10.215.140.1: bytes=32 time=550ms TTL=56
Reply from 10.215.140.1: bytes=32 time=567ms TTL=56
Ping statistics for 10.215.140.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 535ms, Maximum = 858ms, Average = 598ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com - ok
www.google.com – ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Rogerio Esteves Nunes
Função: Secretario
MASP: 1058827-5
Telefone: 33-988133497
Telefolic. 33-700133471
Funcionamento: 07:00h às 12:00h