

# **TERMO DE ACEITE TÉCNICO**

Solicitante: VIVO- Projeto Escolas Rurais

NOC/Operador: Wallace Teixeira

Cliente: Vivo

Empresa
EMC Brasil
VIVO-PER-26158469-PE
VIVO-PER-26158469-PE
VIVO-PER-26158469-PE
VIVO-PER-26158469-PE
VIVO-PER-26158469-PE



# dvb tx show

## Satellite (DVB) TX Configuration

Auto start : Enabled

IDU Output Power : -15 dBm IDU Max Output Power: 0.0 dBm

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : None

### Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)

IDU Output Power : -14.8 dBm Es/No : 11.0 dB

Header Compression : Disabled

Timing correction : -21 us (251456 us)

Frequency correction: 50 Hz

#### Satellite (DVB) RX Configuration

-----

Auto start : Enabled

Max MODCOD : 23 16APSK-9/10 (SNR threshold: 23.5 dB)

Missing ACM/VCM config from HUB

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId Sat[Id/Pos] Enable
\* 0 0 25.333333 12.050000 DVB-S2 102 0/ 0.0 E Yes
7 7 30.000000 12.050000 DVB-S2 102 0/ 0.0 E Yes

#### Satellite (DVB) Receiver Status

-----

Rx State : On

DVB State : Forward link up
Network : 1326, T14R Beam
Frequency : 12.050008 GHz
Symbol Rate : 25.333011 Msps

S2 ModCod

- receiving : 12 8PSK-3/5 - current max : 15 8PSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
Roll off : 0.20
SNR : 15.2 dB
Input Power : -34 dBm

```
Microsoft Windows [versão 10.0.15063]
(c) 2017 Microsoft Corporation. Todos os direitos reservados.

C:\Users\Bruno Barros>ping 8.8.8.8

Disparando 8.8.8.8 com 32 bytes de dados:
Resposta de 8.8.8.8: bytes=32 tempo-901ms TTL=43
Resposta de 8.8.8.8: bytes=32 tempo-902ms TTL=43
Resposta de 8.8.8.8: bytes=32 tempo-902ms TTL=43
Resposta de 8.8.8.8: bytes=32 tempo-902ms TTL=43
Resposta de 8.8.8.8: bytes=32 tempo-91ms TTL=43
Resposta de 8.8.8.8: bytes=32 tempo-92ms TTL=43
Resposta de 8.8.8.8: bytes=32 tempo-92m
```