


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Sergio Almeida

GRE/Prodemge: João Antinossi Responsável/cliente: Nilma Ferreira

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-MOOS-22746 2Mbps **VSAT**



Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State

Network

: On : Forward link up : 65281, Prodemge@Vodanet : 12.176406 GHz : 4.882908 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.1 dB Input Power : -34 dBm

```
Satellite (DVB) TX Configuration
-----
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                   : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                   : On (DVB-RCS2)
State
IDU Output Power : -17.2 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.4 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -393 us (281335 us)
Frequency correction: 50 Hz
System Information:
                   : SEE-MOOS-22746
   Name
    Location
                       : Montes Claros - MG
    Contact
   System Up time : 0 days, 00:14:52 CPU Load : 8%
                       : 18 November 2017 14:15:16
    System time(UTC)
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
                       : 120033
    HW ID
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4c:48
Satellite (DVB) : 00:20:0e:10:4c:48
NetAddr
            State MacAddr
     10.214.2.2 Dynamic c8:3a:35:00:d7:68 1
Pinging 10.214.2.1 with 32 bytes of data:
Reply from 10.214.2.1: bytes=32 time=551ms TTL=56
Reply from 10.214.2.1: bytes=32 time=667ms TTL=56
Reply from 10.214.2.1: bytes=32 time=567ms TTL=56
Reply from 10.214.2.1: bytes=32 time=646ms TTL=56
Reply from 10.214.2.1: bytes=32 time=564ms TTL=56
Reply from 10.214.2.1: bytes=32 time=556ms TTL=56
Reply from 10.214.2.1: bytes=32 time=541ms TTL=56
Reply from 10.214.2.1: bytes=32 time=567ms TTL=56
Reply from 10.214.2.1: bytes=32 time=536ms TTL=56
Reply from 10.214.2.1: bytes=32 time=585ms TTL=56
Ping statistics for 10.214.2.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 536ms, Maximum = 667ms, Average = 578ms
```

Lista de sites acessados: www.globo.com – ok www.yahoo.com – ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br – ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Nilma Ferreira Função: ATB MASP: 13624069 Telefone: 38-998034838 Funcionamento: 07:00 as 22:00