

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Fabrinne Dantas Lanokamme

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-NAUE-22934 2Mbps

Port eth0 on SEE-NAUE-22934 (10.215.127.1)



Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 03201, : 12.176642 GHz : 4.883083 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.7 dB Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -14.8 dBm
ODU Output Power : 33.3 dBm
EIRP
                     : 46.6 dBW
Es/No
                     : 12.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -219 us (280252 us)
Frequency correction: 100 Hz
System Information:
    Name
                        : SEE-NAUE-22934
    Location
                         : Nanuque - MG
    Contact
    System Up time : 0 days, 00:26:51

CPU Load : 15%

System time(UTC) : 29 November 2017 16:37:38
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                         : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4a:cc Satellite (DVB) : 00:20:0e:10:4a:cc
    Ethernet (LAN)
NetAddr
           State MacAddr
   10.215.127.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.215.127.1 with 32 bytes of data:
Reply from 10.215.127.1: bytes=32 time=636ms TTL=56
Reply from 10.215.127.1: bytes=32 time=607ms TTL=56
Reply from 10.215.127.1: bytes=32 time=589ms TTL=56
Reply from 10.215.127.1: bytes=32 time=561ms TTL=56
Reply from 10.215.127.1: bytes=32 time=582ms TTL=56
Reply from 10.215.127.1: bytes=32 time=551ms TTL=56
Reply from 10.215.127.1: bytes=32 time=581ms TTL=56
Reply from 10.215.127.1: bytes=32 time=638ms TTL=56
Reply from 10.215.127.1: bytes=32 time=560ms TTL=56
Reply from 10.215.127.1: bytes=32 time=624ms TTL=56
Ping statistics for 10.215.127.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 551ms, Maximum = 638ms, Average = 592ms
```

T' (1)' () and an
Lista de sites acessados: www.globo.com – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
www.prodernge.gov.br
Responsável pelo teste de navegação:
Nome: Fabrinne Dantas Lanokammer
Função: Diretora
MASP: 1064831-9
Telefone: 33-991910419
Funcionamento: 06:00h às 23:00h