

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Gustavo Oliveira

GRE/Prodemge: João Antinossi Responsável/cliente Fabio Hernane dos Santos

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **SEE-POHA-22549** VSAT 2Mbps





SatLink 2000

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdox

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status ______

Rx State : On

DVB State : Forward link up

Network

: 65281, Prodemge@Vodanet : 12.176598 GHz Frequency Symbol Rate : 4.882982 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On

```
Frame length
                   : Short
                   : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                   : 16.7 dB
SNR
Input Power
                   : -28 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled : DU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -18.4 dBm
ODU Output Power : 32.7 dBm
EIRP
                   : 46.0 dBW
Es/No
                   : 14.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -387 us (280795 us)
Frequency correction: 10 Hz
# arp show
                State MacAddr
   NetAddr
                                           Ιf
   10.213.132.2 Dynamic 64:1c:67:61:83:29 1
# device show
System Information:
   Name
                      : SEE-POHA-22549
    Location
                       : Porteirinha - MG
    Contact
   System Up time : 0 days, 00:22:09
CPU Load : 8%
System time(UTC) : 11 November 2017 12:57:07
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5d:29
    Satellite (DVB)
                       : 00:20:0e:10:5d:29
Pinging 10.213.132.1 with 32 bytes of data:
Reply from 10.213.132.1: bytes=32 time=536ms TTL=56
Reply from 10.213.132.1: bytes=32 time=567ms TTL=56
Reply from 10.213.132.1: bytes=32 time=587ms TTL=56
Reply from 10.213.132.1: bytes=32 time=582ms TTL=56
Reply from 10.213.132.1: bytes=32 time=578ms TTL=56
Reply from 10.213.132.1: bytes=32 time=569ms TTL=56
Reply from 10.213.132.1: bytes=32 time=570ms TTL=56
Reply from 10.213.132.1: bytes=32 time=516ms TTL=56
Reply from 10.213.132.1: bytes=32 time=585ms TTL=56
Reply from 10.213.132.1: bytes=32 time=555ms TTL=56
```

Ping statistics for 10.213.132.1: Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 516ms, Maximum = 587, Average = 594ms Lista de sites acessados: www.globo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok Responsável pelo teste de navegação: Nome: Fabio Hernane dos Santos Função: Diretor Identidade: MASP: 1.278.091-2 Telefone: (38) 9 9809-0071 Horario: 07:00 às 18:00