


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes **Operadora/Cliente: Ederson Martins** 

GRE/Prodemge: João Antinossi Responsável/cliente: Maurilei Neves de Araujo

> Consórcio **VSAT-ID** Porta kbps **Plataforma EMC/Vodanet** SEE-SACO-22218 2Mbps **VSAT**



Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 \* 0 0 0 0.0 E

Yes

16.667000 1 11.962753 DVB-S2 2 0 0.0 E 1

Yes

Satellite (DVB) Receiver Status

\_\_\_\_\_

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176135 GHz Frequency Symbol Rate : 4.882980 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short
DVB S2 Mode : ACM : ACM DVB S2 Mode DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.3 dB

```
Input Power
                 : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -19.3 dBm

ODU Output Power : 32.6 dBm

EIRP
_____
Es/No
                     : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -363 us (281606 us)
Frequency correction: 130 Hz
# device show
System Information:
             : SEE-SACO-22218
    Name
    Location
                        : SÃO FRANCISCO - MG
    Contact
    System Up time : 0 days, 00:18:20 CPU Load : 15%
    System time (UTC) : 26 October 2017 16:15:23
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
                        : 120033
    HW ID
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4c:e5
Satellite (DVB) : 00:20:0e:10:4c:e5
# arp show
                State MacAddr
    10.213.17.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.17.1 with 32 bytes of data:
Reply from 10.213.17.1: bytes=32 time=559ms TTL=56
Reply from 10.213.17.1: bytes=32 time=561ms TTL=56
Reply from 10.213.17.1: bytes=32 time=563ms TTL=56
Reply from 10.213.17.1: bytes=32 time=569ms TTL=56
Reply from 10.213.17.1: bytes=32 time=593ms TTL=56
Reply from 10.213.17.1: bytes=32 time=576ms TTL=56
Reply from 10.213.17.1: bytes=32 time=552ms TTL=56
Reply from 10.213.17.1: bytes=32 time=526ms TTL=56
Reply from 10.213.17.1: bytes=32 time=628ms TTL=56
Reply from 10.213.17.1: bytes=32 time=553ms TTL=56
Ping statistics for 10.213.17.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
```

Approximate round trip times in milli-seconds:
Minimum = 526ms, Maximum = 628ms, Average = 568ms
Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
www.prodernge.gov.br
Responsável pelo teste de navegação:
Nome: Maurilei Neves de Araujo
Função: Diretor RG: 10158173
Telefone 38-3631-5107
Telefone 38-3031-3107
F '
Funcionamento: 07:00 às 12:00h