prodemge	**TERMO DE ACEITE TÉCNICO**

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior	**Operadora/Cliente RodrigoAlves**
GRE/Prodemge: João Antinossi	**Responsável/cliente** Wauder Ramos Ferreira

Consórcio EMC/Vodanet	**VSAT-ID** SEE-COUS-22992	**Porta kbps** 2Mbps	**Plataforma** VSAT

Port eth0 SEE- SEE-COUS-22992(10.215.200.1)

SatLink 2000
- Main board ID 120026, Revision R6.1
- SW ID 120208, Revision 16.0.1 Build 57
dvb tx show

Satellite (DVB) TX Configuration

Auto start   : Enabled
IDU Output Power   : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power   : 33.2 dBm
EIRP   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode   : VC-Mux
Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State   : On (DVB-RCS2)
IDU Output Power   : -16.9 dBm
ODU Output Power   : 32.9 dBm
EIRP   : 46.2 dBW
Es/No   : 12.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction   : -231 us (281616 us)
Frequency correction: 90 Hz
dvb rx show

Satellite (DVB) RX Configuration

Auto start   : Enabled

Max Traffic MODCOD   : 23   16APSK-9/10
RX watchdog   : 15 minute

Idx	Pri	SymbRate[Msps]	Freq[GHz]	Mode	PopId	SatId	Pos	SatName	Name Enable
* 0	0	4.883300	12.176420	DVB-S2	104	0	0.0 E		Yes

Satellite (DVB) Receiver Status

Rx State   : On
DVB State   : Forward link up
Network   : 65281, Prodemge@Vodanet
Frequency   : 12.176527 GHz
Symbol Rate   : 4.883009 Msps
S2 ModCod
   - receiving : 19   16APSK-3/4
   - current max : 21   16APSK-5/6
Pilot   : On
Frame length   : Short
DVB S2 Mode   : ACM
DVB S2 Stream type : MPEG-TS
Roll off   : 0.20
SNR   : 16.4 dB
Input Power   : -37 dBm
arp show

  NetAddr   State   MacAddr   If
  10.215.200.2 Dynamic 2c:27:d7:a0:cd:ed   1
device show
System Information:
   Name   : SEE-COUS-22992
   Location   : Cora▓▓o de Jesus - MG
   Contact   :
   System Up time   : 0 days, 00:13:29
   CPU Load   : 18%
   System time(UTC)   : 20 November 2017 21:02:01
   Broadcast Message   : not set

HW:
   Model   : SatLink 2000
   HW ID   : 120033
   Main board ID   : 120026 R6.1

MAC addresses:
   Ethernet (LAN)   : 00:20:0e:10:48:8d
   Satellite (DVB)   : 00:20:0e:10:48:8d

Pinging 10.215.200.1 with 32 bytes of data:

Reply from 10.215.200.1: bytes=32 time=571ms TTL=56
Reply from 10.215.200.1: bytes=32 time=550ms TTL=56
Reply from 10.215.200.1: bytes=32 time=631ms TTL=56
Reply from 10.215.200.1: bytes=32 time=529ms TTL=56
Reply from 10.215.200.1: bytes=32 time=545ms TTL=56
Reply from 10.215.200.1: bytes=32 time=613ms TTL=56
Reply from 10.215.200.1: bytes=32 time=585ms TTL=56
Reply from 10.215.200.1: bytes=32 time=529ms TTL=56
Reply from 10.215.200.1: bytes=32 time=562ms TTL=56
Reply from 10.215.200.1: bytes=32 time=569ms TTL=56

Ping statistics for 10.215.200.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
   Minimum = 529ms, Maximum = 631ms, Average = 568ms

www.yahoo.com.br

www.hotmail.com

www.google.com

Responsável	Wauder Ramos Ferreira
Cargo	Diretora
Identidade	9706797
Telefone	038-9-9202-2543
Funcionamento	07:00-22:00
Onde ficou	Secretaria