

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Wallace Teixeira Operadora/Cliente: João Gustavo F M Sobrinho

GRE/Prodemge: João Antinossi Responsável/cliente: Cristier Dias Lu Sena

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SASA-231302MbpsVSAT

## Port eth0 on SEE-SASA-23130 (10.214.49.1)



```
# dvb rx show
```

Satellite (DVB) RX Configuration

-----

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network: 65281, Prodemge@Vodanet

Frequency: 12.176552 GHz Symbol Rate: 4.883065 Msps

S2 ModCod

- receiving : 4 QPSK-1/2
- current max : 21 16APSK-5/6

Pilot : On

Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

```
Roll off: 0.20
SNR : 15.4 dB
Input Power: -34 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -13.7 dBm
ODU Output Power: 35.4 dBm
EIRP: 48.7 dBW
Es/No : 15.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction: -123 us (279704 us)
Frequency correction: -120 Hz
# device show
System Information:
Name: SEE-SASA-23130
Location : SALTO DA DIVISA - MG
Contact :
System Up time: 0 days, 07:39:02
CPU Load : 6%
System time(UTC): 10 December 2017 05:07:35
Broadcast Message : not set
Model : SatLink 2000
HW ID : 120033
Main board ID : 120026 R6.1
MAC addresses:
Ethernet (LAN): 00:20:0e:10:49:c9
Satellite (DVB) : 00:20:0e:10:49:c9
Transec not Supported by this device !
# arp show
NetAddr State MacAddr If
Pinging 10.214.49.1 with 32 bytes of data:
Reply from 10.214.49.1: bytes=32 time=551ms TTL=56
Reply from 10.214.49.1: bytes=32 time=572ms TTL=56
Reply from 10.214.49.1: bytes=32 time=595ms TTL=56
Reply from 10.214.49.1: bytes=32 time=558ms TTL=56
Reply from 10.214.49.1: bytes=32 time=602ms TTL=56
Reply from 10.214.49.1: bytes=32 time=533ms TTL=56
Reply from 10.214.49.1: bytes=32 time=614ms TTL=56
Reply from 10.214.49.1: bytes=32 time=566ms TTL=56
Reply from 10.214.49.1: bytes=32 time=542ms TTL=56
Reply from 10.214.49.1: bytes=32 time=546ms TTL=56
Ping statistics for 10.214.49.1:
Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
Minimum = 533ms, Maximum = 614ms, Average = 567ms
```

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.google.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok
desponsável pelo teste de navegação: Nome: Cristier Dias Lu Sena Nunção: EEB Supervisão Identidade: MASP:9784141-1