

## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

Consórcio

EMC/Vodanet


NOC/Operadora: Paulo de Tarso Operadora/Cliente: Gilvan P de Brito Júnior

VSAT-ID

SEE-JABA-22527

Responsável/cliente: João Vanderlucio Ferreira GRE/Prodemge: João Antinossi Oliveira

Porta kbps **Plataforma** 2048/1024 VSAT



PRTG Traffic Grapher V6.2.0.907 - 4/11/2017 16:37:58

Satellite (DVB) RX Configuration -----

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

: 12.176280 GHz : 4.883066 Msps Frequency Symbol Rate : 4.883066 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short Frame length : Shor DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.5 dB Input Power : -31 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 14.150500 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -14.9 dBm

ODU Output Power : 34.4 dBm

EIRP
_____
Es/No
                   : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -386 us (281158 us)
Frequency correction: 130 Hz
System Information:
   Name
                       : SEE-JABA-22527
    Location
                       : JAÍBA - MG
    Contact
   System Up time : 0 days, 01:29:30 CPU Load : 9%
    System time(UTC) : 04 November 2017 15:46:26
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
   MAC addresses:
Pinging 10.213.110.1 with 32 bytes of data:
Reply from 10.213.110.1: bytes=32 time=565ms TTL=56
Reply from 10.213.110.1: bytes=32 time=562ms TTL=56
Reply from 10.213.110.1: bytes=32 time=557ms TTL=56
Reply from 10.213.110.1: bytes=32 time=581ms TTL=56
Reply from 10.213.110.1: bytes=32 time=535ms TTL=56
Reply from 10.213.110.1: bytes=32 time=568ms TTL=56
Reply from 10.213.110.1: bytes=32 time=544ms TTL=56
Reply from 10.213.110.1: bytes=32 time=579ms TTL=56
Reply from 10.213.110.1: bytes=32 time=567ms TTL=56
Reply from 10.213.110.1: bytes=32 time=573ms TTL=56
Ping statistics for 10.213.110.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 535ms, Maximum = 581ms, Average = 563ms
NetAddr
         State MacAddr
   10.213.110.2 Dynamic e8:9a:8f:b7:bd:4a 1
```

## Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com – ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: João Vanderlucio Ferreira Oliveira Função: Diretor Telefone: 38 -9 9121-9007 MASP 812303-6 Horário de Funcionamento: 7:00 ás 17:30