


TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gustavo de Oliveira

GRE/Prodemge: João Antinossi Responsável/cliente: Gildasio Barbosa Sena

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-SEHA-22970 2Mbps **VSAT**





Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status ______

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65281, ... : 12.176560 GHz : 4.883003 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.3 dB Input Power : -29 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -21.5 dBm
ODU Output Power : 32.8 dBm
EIRP
                    : 46.1 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -350 us (280892 us)
Frequency correction: 110 Hz
System Information:
                       : SEE-SEHA-22970
    Name
    Location
                        : Setubinha - MG
    Contact
    System Up time : 0 days, 00:21:31 CPU Load : 14%
    System time(UTC) : 29 November 2017 13:48:25
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4f:46
Satellite (DVB) : 00:20:0e:10:4f:46
    Ethernet (LAN)
NetAddr
          State MacAddr
   10.215.169.2 Dynamic 64:1c:67:61:83:29 1
Pinging 10.215.169.1 with 32 bytes of data:
Reply from 10.215.169.1: bytes=32 time=554ms TTL=56
Reply from 10.215.169.1: bytes=32 time=571ms TTL=56
Reply from 10.215.169.1: bytes=32 time=519ms TTL=56
Reply from 10.215.169.1: bytes=32 time=587ms TTL=56
Reply from 10.215.169.1: bytes=32 time=605ms TTL=56
Reply from 10.215.169.1: bytes=32 time=544ms TTL=56
Reply from 10.215.169.1: bytes=32 time=542ms TTL=56
Reply from 10.215.169.1: bytes=32 time=550ms TTL=56
Ping statistics for 10.215.169.1:
    Packets: Sent = 8, Received = 8, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 519ms, Maximum = 605ms, Average = 559ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok <u>www.yahoo.com</u> – ok <u>www.hotmail.com</u> – ok www.google.com – ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Gildasio Barbosa Sena Função: Secretario MASP: 859778-3 Telefone: 33-98812-7741 Funcionamento: 07:00h às 16:30h