

# TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Ermínio Junior

Operadora/Cliente Eduardo Tarda

Responsável/cliente Juliana keila Fontes
Mattos

Consórcio VSAT-ID Porta kbps
EMC/Vodanet SEE-TENI-22989 2Mbps VSAT

Port eth0 SEE-TENI-22989 (10.215.190.1)



#### # dvb tx show

## Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz ATM mode : VC-Mux

Header Compression : UDP/IP

## Satellite (DVB) Transmitter Status

-----

State : On (DVB-RCS2)
IDU Output Power : -19.0 dBm
ODU Output Power : 33.3 dBm
EIRP : 46.6 dBW
Es/No : 11.5 dB

Header Compression  $\,:$  Disabled  $\,$  - HC for RCS2 not supported by HUB

Timing correction : -330 us (280607 us)

Frequency correction: 30 Hz

# dvb rx show

### Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Name

Yes

Yes

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Enable 12.176420 DVB-S2 104 \*00 4.883300 0 0.0 E 11.962753 DVB-S2 2 0.00E1 1 16.667000 Satellite (DVB) Receiver Status Rx State : On **DVB** State : Forward link up Network : 65281, Prodemge@Vodanet : 12.176208 GHz Frequency Symbol Rate : 4.883000 Msps S2 ModCod - receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6 Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS Roll off : 0.20 **SNR** : 16.9 dB Input Power : -34 dBm # arp show State MacAddr NetAddr 10.215.190.2 Dynamic b8:70:f4:6e:b3:ab 1 # device show System Information: : SEE-TENI-22989 Name Location : TE FILO OTONI Contact System Up time : 0 days, 00:13:04 : 14% CPU Load System time(UTC) : 25 November 2017 12:57:36 Broadcast Message : not set HW: Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.2 MAC addresses: Ethernet (LAN) : 00:20:0e:10:5b:1f Satellite (DVB) : 00:20:0e:10:5b:1f Pinging 10.215.190.1 with 32 bytes of data: Reply from 10.215.190.1: bytes=32 time=566ms TTL=56 Reply from 10.215.190.1: bytes=32 time=545ms TTL=56 Reply from 10.215.190.1: bytes=32 time=556ms TTL=56 Reply from 10.215.190.1: bytes=32 time=549ms TTL=56 Reply from 10.215.190.1: bytes=32 time=577ms TTL=56 Reply from 10.215.190.1: bytes=32 time=527ms TTL=56 Reply from 10.215.190.1: bytes=32 time=539ms TTL=56 Reply from 10.215.190.1: bytes=32 time=597ms TTL=56 Reply from 10.215.190.1: bytes=32 time=573ms TTL=56 Reply from 10.215.190.1: bytes=32 time=554ms TTL=56 Ping statistics for 10.215.190.1: Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 527ms, Maximum = 597ms, Average = 558ms www.hotmail.com

www.google.com

www.prodemge.gov.br

## www.globo.com

# www.youtube.com

Nome do responsável : Juliana keila Fontes Mattos

Telefone: (33) 35282180

Cargo: diretora

MASP: 1096660-4

Horário de funcionamento: da: 07:00 as 17:00 horas

Modem fica conectado onde: Computador sala digital