


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Wallace Teixeira Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: DILMA LOPES DE SOUZA

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-NORO-22939 2MBPS **VSAT**



dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176398 GHz

Symbol Rate : 4.883033 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS

```
Roll off
                    : 0.20
SNR
                   : 16.2 dB
Input Power
                   : -30 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                   : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.7 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.4 dBW
Es/No
                    : 12.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -169 us (280855 us)
Frequency correction: -60 Hz
# device show
System Information:
            : SEE-NORO-22939
   Name
    Location
                       : Novo Cruzeiro - MG
    Contact
                       :
   System Up time : 0 days, 05:01:56
CPU Load : 8%
    System time(UTC) : 23 November 2017 03:22:59
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:55:1f
Satellite (DVB) : 00:20:0e:10:55:1f
# arp show
   NetAddr State MacAddr
                                           Ιf
Pinging 10.215.132.1 with 32 bytes of data:
Reply from 10.215.132.1: bytes=32 time=570ms TTL=56
Reply from 10.215.132.1: bytes=32 time=527ms TTL=56
Reply from 10.215.132.1: bytes=32 time=560ms TTL=56
Reply from 10.215.132.1: bytes=32 time=550ms TTL=56
Reply from 10.215.132.1: bytes=32 time=562ms TTL=56
Reply from 10.215.132.1: bytes=32 time=527ms TTL=56
Reply from 10.215.132.1: bytes=32 time=578ms TTL=56
Reply from 10.215.132.1: bytes=32 time=558ms TTL=56
Reply from 10.215.132.1: bytes=32 time=551ms TTL=56
Reply from 10.215.132.1: bytes=32 time=561ms TTL=56
Ping statistics for 10.215.132.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
```

Approximate round trip times in milli-seconds: Minimum = 527ms, Maximum = 578ms, Average = 554ms
Lista de sites acessados:
www.globo.com – ok
<u>www.yahoo.com</u> – ok
www.hotmail.com - ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
www.proderinge.gov.or
Responsável pelo teste de navegação:
Nome: DILMA LOPES DE SOUZA
Função: DIRETORA
Identidade: MASP: 6388417