

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: João Gustavo

Responsável/cliente: Jaksele Pereira Landim GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet **VSAT** SEE-COHO-22119 2Mbps

Port eth0 on SEE-COHO-22119 (10.212.172.1)



Satellite (DVB) RX Configuration -----Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 0 0.0 E 16.667000 11.962753 DVB-S2 2

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176282 GHz

Symbol Rate : 4.883040 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stroom DVB S2 Stream type : MPEG-TS

```
: 0.20
Roll off
SNR
                    : 17.0 dB
Input Power
                    : -28 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.7 dBm
ODU Output Power : 32.9 dBm
EIRP
                    : 46.2 dBW
EIRP
                    : 11.5 dB
Es/No
\hbox{\tt Header Compression} \quad \hbox{\tt : Disabled} \quad \hbox{\tt - HC for RCS2 not supported by HUB}
Timing correction : -418 us (281391 us)
Frequency correction: 90 Hz
# device show
System Information:
                    : SEE-COHO-22119
   Name
    Location
                        : C nego Marinho - MG
    Contact
    System Up time : 18 days, 14:33:05 CPU Load : 15%
    System time(UTC) : 23 November 2017 14:15:14 Broadcast Message : not set
HW:
   Model
                        : SatLink 2000
    HW ID
                        : 120033
   Main board ID
                      : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5f:4b
Satellite (DVB) : 00:20:0e:10:5f:4b
# arp show
   NetAddr
             State MacAddr
   10.212.172.2 Dynamic b8:70:f4:6e:b3:ab 1
Pinging 10.212.172.1 with 32 bytes of data:
Reply from 10.212.172.1: bytes=32 time=578ms TTL=56
Reply from 10.212.172.1: bytes=32 time=547ms TTL=56
Reply from 10.212.172.1: bytes=32 time=597ms TTL=56
Reply from 10.212.172.1: bytes=32 time=580ms TTL=56
Reply from 10.212.172.1: bytes=32 time=535ms TTL=56
Reply from 10.212.172.1: bytes=32 time=540ms TTL=56
Reply from 10.212.172.1: bytes=32 time=583ms TTL=56
Reply from 10.212.172.1: bytes=32 time=537ms TTL=56
Reply from 10.212.172.1: bytes=32 time=617ms TTL=56
```

```
Ping statistics for 10.212.172.1:
    Packets: Sent = 9, Received = 9, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 535ms, Maximum = 617ms, Average = 568ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Jaksele Pereira Landim

Função: Diretora MASP: 11138476

Contato: (38) 99920-0780

Horário de funcionamento: 06:00 às 18:00h