


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Sergio Almeida

GRE/Prodemge: João Antinossi Responsável/cliente: Normando santos

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-LAOS-220652MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 14/10/2017 16:16:50

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176018 GHz Symbol Rate : 4.883044 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 16 8PSK-8/9

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

: 0.20 Roll off SNR : 15.3 dB Input Power : -37 dBm

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression: UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -16.0 dBm ODU Output Power : 32.7 dBm

EIRP : 46.0 dBW Es/No : 14.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -374 us (281770 us)

Frequency correction: 110 Hz

System Information:

Name : SEE-LAOS-22065

Location : L Contact : : LAGOA DOS PATOS - MG

System Up time : 0 days, 00:20:03

CPU Load : 6%

System time(UTC) : 14 October 2017 15:23:56

Broadcast Message : not set

HW:

: SatLink 2000 Model HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:55:38 Satellite (DVB) : 00:20:0e:10:55:38

arp show

NetAddr State MacAddr If 10.212.137.2 Dynamic 74:e6:e2:d4:e4:73 1

```
Pinging 10.212.137.1 with 32 bytes of data:
Reply from 10.212.137.1: bytes=32 time=584ms TTL=56
Reply from 10.212.137.1: bytes=32 time=579ms TTL=56
Reply from 10.212.137.1: bytes=32 time=606ms TTL=56
Reply from 10.212.137.1: bytes=32 time=588ms TTL=56
Reply from 10.212.137.1: bytes=32 time=638ms TTL=56
Reply from 10.212.137.1: bytes=32 time=590ms TTL=56
Reply from 10.212.137.1: bytes=32 time=618ms TTL=56
Reply from 10.212.137.1: bytes=32 time=567ms TTL=56
Reply from 10.212.137.1: bytes=32 time=595ms TTL=56
Reply from 10.212.137.1: bytes=32 time=571ms TTL=56
Ping statistics for 10.212.137.1:
  Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
  Minimum = 567ms, Maximum = 638ms, Average = 593ms
Sites acessados
www.globo.com ok
www.yahoo.com.br- ok
www.hotmail.com- ok
www.google.com - ok
www.prodemge.gov.br - ok
Nome do responsável: Normando santos- ATB
cargo: Professor
MASP: Rg. mg10 907812
```