

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Gustavo de Oliveira

GRE/Prodemge: João Antinossi Responsável/cliente: Edilson Dourado Santana

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-JAIA-221522MbpsVSAT

Port eth0 on SEE-JAIA-22152 (10.212.205.1)



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176157 GHz
Symbol Rate : 4.883042 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20

```
: 14.8 dB
Input Power
                    : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
-----
State : On (DVB-RCS2)
IDU Output Power : -14.7 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
                    : 13.5 dB
Es/No
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : 46 us (281378 us)
Frequency correction: 180 Hz
# device show
System Information:
    Name
                        : SEE-JAIA-22152
    Location
                        : JANUARIA - MG
    Contact
    System Up time : 0 days, 08:25:01 CPU Load : 16%
    System time(UTC) : 23 November 2017 18:59:33 Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:58:47
Satellite (DVB) : 00:20:0e:10:58:47
# arp show
   NetAddr
             State MacAddr
   10.212.205.2 Dynamic b8:ae:ed:8b:a1:67 1
Pinging 10.212.205.1 with 32 bytes of data:
Reply from 10.212.205.1: bytes=32 time=554ms TTL=56
Reply from 10.212.205.1: bytes=32 time=547ms TTL=56
Reply from 10.212.205.1: bytes=32 time=591ms TTL=56
Reply from 10.212.205.1: bytes=32 time=581ms TTL=56
Reply from 10.212.205.1: bytes=32 time=575ms TTL=56
Reply from 10.212.205.1: bytes=32 time=563ms TTL=56
Reply from 10.212.205.1: bytes=32 time=658ms TTL=56
Reply from 10.212.205.1: bytes=32 time=558ms TTL=56
Reply from 10.212.205.1: bytes=32 time=523ms TTL=56
Reply from 10.212.205.1: bytes=32 time=563ms TTL=56
```

```
Ping statistics for 10.212.205.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 523ms, Maximum = 658ms, Average = 571ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Responsável pelo teste de navegação: Nome: Edilson Dourado Santana

Função: Diretor MASP: 880302-5

Contato: (38) 99962-8965

Horário de funcionamento: 07:00 as 22:00