

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Rodrigo Alves

GRE/Prodemge: João Antinossi Responsável/cliente: Beatisma Laudenilo Neto

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-COUS-22995 2Mbps **VSAT**

Port eth0 on SEE-COUS-22995 (10.215.203.1)



Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

11.962753 DVB-S2 2 0 0.0 E 1 1 16.667000

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 65281, Prodei : 12.176218 GHz Frequency Symbol Rate : 4.883021 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 16.8 dB SNR Input Power : -38 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -30 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -14.2 dBm

ODU Output Power : 33.0 dBm

EIRP
______
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -349 us (281580 us)
Frequency correction: 170 Hz
System Information:
    Name
                        : SEE-COUS-22995
    Location
                        : CORAÇÃO DE JESUS - MG
    Contact
                        :
    System Up time : 0 days, 00:03:27
CPU Load : 8%
System time(UTC) : 24 November 2017 16:53:55
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:53:51
    Satellite (DVB)
                       : 00:20:0e:10:53:51
             State MacAddr
   10.215.203.2 Dynamic 2c:27:d7:a0:cd:ed 1
Pinging 10.215.203.1 with 32 bytes of data:
Reply from 10.215.203.1: bytes=32 time=525ms TTL=56
Reply from 10.215.203.1: bytes=32 time=570ms TTL=56
Reply from 10.215.203.1: bytes=32 time=630ms TTL=56
Reply from 10.215.203.1: bytes=32 time=549ms TTL=56
Reply from 10.215.203.1: bytes=32 time=544ms TTL=56
Reply from 10.215.203.1: bytes=32 time=519ms TTL=56
Reply from 10.215.203.1: bytes=32 time=523ms TTL=56
Reply from 10.215.203.1: bytes=32 time=674ms TTL=56
Reply from 10.215.203.1: bytes=32 time=565ms TTL=56
Reply from 10.215.203.1: bytes=32 time=563ms TTL=56
Ping statistics for 10.215.203.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 519ms, Maximum = 674ms, Average = 566ms
```

Lista de sites acessados:	
www.globo.com – ok	
www.yahoo.com – ok	
www.hotmail.com – ok	
www.google.com – ok	
www.educacao.mg.gov.br – ok	
www.prodemge.gov.br – ok	
Responsável pelo teste de navegação:	
Nome: Beatisma Laudenilo Neto	
Função: Diretora	
MASP: 11851706	
Telefone: 38-99838-5500	
Funcionamento: 07:00h às 10:00h	