


# TERMO DE ACEITE TÉCNICO

Solicitante: VIVO- Projeto Escolas Rurais

NOC/Operador: Rogério Momi Frias Cliente: VIVO

> **Empresa** VSAT-ID Link kbps Plataforma **EMC** Brasil VIVO-PER-28023463-SE 256/128 **VSAT**



## Satellite (DVB) RX Configuration

Auto start : Enabled

Max Signalling MODCOD: 23 16APSK-9/10 Max Traffic MODCOD : 28 32APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable Yes

\* 0 0 9.320000 12.055825 DVB-S2 102 0 0.0 E

#### Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up Network : 1326, T14R Beam Frequency : 12.055895 GHz

Symbol Rate : 9.320246 Msps

S2 ModCod

- receiving : 14 8PSK-3/4 - current max : 15 8PSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 12.5 dB : -38 dBm Input Power

#### Satellite (DVB) TX Configuration

Auto start : Enabled
BUPC status : Disabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : None

### Satellite (DVB) Transmitter Status

-----

State : On (DVB-RCS) IDU Output Power : -20.0 dBm

Es/No : 13.0 dB

Header Compression: Disabled

Timing correction: -151 us (262063 us)

Frequency correction: 110 Hz

```
Resposta de 8.8.8.8: bytes=32 tempo=586ms IIL=43
Resposta de 8.8.8.8: bytes=32 tempo=646ms IIL=43
Resposta de 8.8.8.8: bytes=32 tempo=646ms IIL=43
Resposta de 8.8.8.8: bytes=32 tempo=646ms IIL=43
Resposta de 8.8.8.8: bytes=32 tempo=678ms IIIL=43
Resposta de 8.8.8.8: bytes=32 tempo=678ms IIIL=43
Resposta de 8.8.8.8: bytes=32 tempo=579ms IIIL=43
Resposta de 8.8.8.8: bytes=32 tempo=638ms IIIL=43
Resposta de 8.8.8.8: bytes=32 tempo=640ms IIIL=43
Resposta de 8.8.8.8: bytes=32 tempo=659ms IIIL=43
Resposta de 8.8.8.8: bytes=32 tempo=660ms IIIL=43
Resposta de 8.8.8.8: bytes=32 tempo=660ms IIIL=43
Resposta de 8.8.8.8: bytes=32 tempo=650ms IIIL=43
Resposta de 8.8.8.8: bytes=32 tempo=660ms IIIL=43
```