

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

Operadora/Cliente Joao Carlos


GRE/Prodemge: João Antinossi

Responsável/cliente Rafael Braga

Consórcio
VSAT-ID
EMC/Vodanet

SEE-UBIA-22281

Porta kbps
Plataforma
VSAT



dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -18.9 dBm ODU Output Power : 33.1 dBm

EIRP : 46.4 dBW Es/No : 14.0 dB Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -277 us (281387 us)

Frequency correction: 120 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 $0 \ 0.0 \, \mathrm{E}$

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up
Network : 65281, Prodemge@Vodanet
Frequency : 12.176121 GHz
Symbol Rate : 4.882952 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 15.7 dB Input Power : -35 dBm

arp show

NetAddr State MacAddr If 10.213.80.2 Dynamic 54:04:a6:8e:d3:f6 1

device show

System Information:

Name : SEE-UBAI-22281

Location : UBAI

Contact

System Up time : 0 days, 00:15:42

CPU Load : 7%

System time(UTC) : 21 October 2017 12:29:12

Broadcast Message : not set

HW:

Model : SatLink 2000 : 120033 HW ID

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:56:a9 Satellite (DVB) : 00:20:0e:10:56:a9

Pinging 10.213.80.1 with 32 bytes of data:

Reply from 10.213.80.1: bytes=32 time=524ms TTL=56 Reply from 10.213.80.1: bytes=32 time=545ms TTL=56 Reply from 10.213.80.1: bytes=32 time=509ms TTL=56 Reply from 10.213.80.1: bytes=32 time=506ms TTL=56 Reply from 10.213.80.1: bytes=32 time=560ms TTL=56 Reply from 10.213.80.1: bytes=32 time=576ms TTL=56 Reply from 10.213.80.1: bytes=32 time=586ms TTL=56 Reply from 10.213.80.1: bytes=32 time=553ms TTL=56 Reply from 10.213.80.1: bytes=32 time=521ms TTL=56 Reply from 10.213.80.1: bytes=32 time=538ms TTL=56 Reply from 10.213.80.1: bytes=32 time=538ms TTL=56

Ping statistics for 10.213.80.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 509ms, Maximum = 586ms, Average = 511 ms

#

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável: Rafael Braga da Silveira

Cargo: Diretor

Identidade: 1101255.6