


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Robson Nikitin

Responsável/cliente: Celio de Melo Araujo GRE/Prodemge: João Antinossi

> Consórcio VSAT-ID Plataforma Porta kbps EMC/Vodanet SEE-COHO-22117 2048/1024 **VSAT**



Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status

: On Rx State

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

Frequency Frequency : 12.176205 GHz Symbol Rate : 4.883041 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.1 dB Input Power : -31 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -17.8 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.4 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -390 us (281369 us)
Frequency correction: 170 Hz
System Information:
    Name
                        : SEE-COHO-22117
    Location
                        : C NEGO MARINHO - MG
    Contact
                        :
    System Up time : 0 days, 00:13:50 CPU Load : 18%
    System time (UTC) : 05 November 2017 16:34:44
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:55:02
Satellite (DVB) : 00:20:0e:10:55:02
    Ethernet (LAN)
Pinging 10.212.170.1 with 32 bytes of data:
Reply from 10.212.170.1: bytes=32 time=579ms TTL=56
Reply from 10.212.170.1: bytes=32 time=539ms TTL=56
Reply from 10.212.170.1: bytes=32 time=602ms TTL=56
Reply from 10.212.170.1: bytes=32 time=568ms TTL=56
Reply from 10.212.170.1: bytes=32 time=565ms TTL=56
Reply from 10.212.170.1: bytes=32 time=583ms TTL=56
Reply from 10.212.170.1: bytes=32 time=601ms TTL=56
Reply from 10.212.170.1: bytes=32 time=592ms TTL=56
Reply from 10.212.170.1: bytes=32 time=569ms TTL=56
Reply from 10.212.170.1: bytes=32 time=541ms TTL=56
Ping statistics for 10.212.170.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 539ms, Maximum = 602ms, Average = 573ms
  NetAddr
            State MacAddr
   10.212.170.3 Dynamic e4:be:ed:90:94:9a 1
```

Lista de sites acessados: www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok
Responsável pelo teste de navegação: Nome: Celio de Melo Araujo Função: Professor Telefone: 38- 99628-5363 MASP 664362-1 Horário de Funcionamento: 07:00 AS 21:00