


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Ederson Martins

Responsável/cliente: Rosilene Afonsina Moura **GRE/Prodemge:** João Antinossi

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet SEE-BUIS-22073 **VSAT** 2Mbps



Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State

: Forward link up : 65281, Prodemge@Vodanet Network

Frequency : 12.176517 GHz Symbol Rate : 4.882998 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stroom DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.3 dB Input Power : -39 dBm

```
Satellite (DVB) TX Configuration
 Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -17.1 dBm
ODU Output Power : 33.9 dBm
EIRP
                     : 46.9 dBW
Es/No
                     : 14.5 dB
{\tt Header\ Compression} : Disabled - HC for RCS2 not supported by HUB
Timing correction : -1179 us (281698 us)
Frequency correction: 100 Hz
System Information:
   Name
                        : SEE-BUIS-22073
    Location
                         : BUENÓPOLIS
    Contact
    System Up time : 0 days, 00:05:35

CPU Load : 11%

System time(UTC) : 04 October 2017 12:56:43
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                        : 120033
                        : 120026 R6.2
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:52:b6
Satellite (DVB) : 00:20:0e:10:52:b6
Disparando 10.148.0.9 com 32 bytes de dados:
Resposta de 10.148.0.9: bytes=32 tempo=595ms TTL=57
Resposta de 10.148.0.9: bytes=32 tempo=561ms TTL=57
Resposta de 10.148.0.9: bytes=32 tempo=560ms TTL=57
Resposta de 10.148.0.9: bytes=32 tempo=567ms TTL=57
Resposta de 10.148.0.9: bytes=32 tempo=555ms TTL=57
Resposta de 10.148.0.9: bytes=32 tempo=672ms TTL=57
Resposta de 10.148.0.9: bytes=32 tempo=603ms TTL=57
Resposta de 10.148.0.9: bytes=32 tempo=560ms TTL=57
Resposta de 10.148.0.9: bytes=32 tempo=569ms TTL=57
Resposta de 10.148.0.9: bytes=32 tempo=588ms TTL=57
Estatísticas do Ping para 10.148.0.9:
    Pacotes: Enviados = 10, Recebidos = 10, Perdidos = 0 (0% de
             perda),
Aproximar um número redondo de vezes em milissegundos:
    Mínimo = 555ms, Máximo = 672ms, Média = 583ms
```

Lista de sites acessados:	
www.globo.com – ok	
<u>www.hotmail.com</u> – ok	
www.google.com – ok	
<u>www.educacao.mg.gov.br</u> – ok	
Responsável pelo teste de navegação: Nome: Rosilene Afonsina Moura Sousa Função: Vice Diretora Identidade: 11628481	