

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Ermínio Junior

Operadora/Cliente Sergio Almeida

GRE/Prodemge: João Antinossi

Responsável/cliente Jamile Mendes

Consórcio
VSAT-ID
Porta kbps
Plataforma
EMC/Vodanet
SEE-MOOS-22577
2Mbps
VSAT



SatLink 2000

- Main board ID 120026, Revision R6.1

- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes
1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176175 GHz Symbol Rate : 4.883000 Msps S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off
            : 0.20
SNR
             : 15.2 dB
               : -35 dBm
Input Power
# dvb tx show
Satellite (DVB) TX Configuration
             : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
             : 46.5 dBW
Default CW Frequency: 0.000000 GHz
               : VC-Mux
ATM mode
Header Compression: UDP/IP
Satellite (DVB) Transmitter Status
           : On (DVB-RCS2)
State
IDU Output Power : -16.1 dBm
ODU Output Power : 33.1 dBm
EIRP
             : 46.4 dBW
             : 13.5 dB
Es/No
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction : -420 us (281385 us)
Frequency correction: -10 Hz
# arp show
 NetAddr
            State MacAddr
 10.213.229.2 Dynamic 74:e6:e2:d4:e4:73 1
# device show
System Information:
               : SEE-MOOS-22577
  Name
                : MONTES CLAROS
  Location
  Contact
  System Up time : 0 days, 00:07:04
CPU Load : 19%
  System time(UTC) : 06 November 2017 13:10:08
  Broadcast Message : not set
HW:
  Model
                : SatLink 2000
  HW ID
                : 120033
  Main board ID
                 : 120026 R6.1
MAC addresses:
  Ethernet (LAN)
                  : 00:20:0e:10:4a:34
  Satellite (DVB) : 00:20:0e:10:4a:34
Pinging 10.213.229.1 with 32 bytes of data:
Reply from 10.213.229.1: bytes=32 time=523ms TTL=56
Reply from 10.213.229.1: bytes=32 time=513ms TTL=56
Reply from 10.213.229.1: bytes=32 time=592ms TTL=56
Reply from 10.213.229.1: bytes=32 time=598ms TTL=56
Reply from 10.213.229.1: bytes=32 time=538ms TTL=56
Reply from 10.213.229.1: bytes=32 time=599ms TTL=56
Reply from 10.213.229.1: bytes=32 time=568ms TTL=56
Reply from 10.213.229.1: bytes=32 time=567ms TTL=56
Reply from 10.213.229.1: bytes=32 time=584ms TTL=56
Reply from 10.213.229.1: bytes=32 time=520ms TTL=56
Ping statistics for 10.213.229.1:
  Packets: Sent = 10, Received = 10, Lost = 0 (0\% loss),
Approximate round trip times in milli-seconds:
  Minimum = 513ms, Maximum = 599ms, Average = 560ms
www.globo.com
www.yahoo.com.br
```

www.hotmail.com www.google.com

www.prodemge.gov.br

Responsável	Jamile Mendes
Cargo	Diretora
Identidade	9592635
Telefone	038-3215-3229
Funcionamento	07:00 às 17:00