


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Wallace Teixeira Operadora/Cliente: João Carlos widar

GRE/Prodemge: João Antinossi Responsável/cliente: José dos Santos Saraiva

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet 2MBPS **VSAT** SEE-ICAS-22125



PRTG Traffic Grapher V6.2.0.907 - 23/10/2017 23:53:27

Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176307 GHz

Symbol Rate : 4.882968 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot : Short Frame length DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS : 0.20 Roll off SNR : 17.9 dB

```
Input Power
                 : -28 dBm
# dvb tx show
Satellite (DVB) TX Configuration
______
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
                    : Enabled
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -15.5 dBm

ODU Output Power : 33.4 dBm

EIRP
_____
Es/No
                     : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -224 us (281734 us)
Frequency correction: -10 Hz
# device show
System Information:
              : SEE-ICAS-22125
    Name
    Location
                        : ICARAI DE MINAS
    Contact
    System Up time : 0 days, 07:18:34 CPU Load : 8%
    System time(UTC) : 23 October 2017 23:23:30
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
                        : 120026 R6.2
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:58:33
Satellite (DVB) : 00:20:0e:10:58:33
    Ethernet (LAN)
# arp show
                State MacAddr
   10.212.178.2 Dynamic 54:04:a6:8e:d3:f6 1
Pinging 10.148.0.171 with 32 bytes of data:
Reply from 10.148.0.171: bytes=32 time=649ms TTL=62
Reply from 10.148.0.171: bytes=32 time=581ms TTL=62
Reply from 10.148.0.171: bytes=32 time=578ms TTL=62
Reply from 10.148.0.171: bytes=32 time=538ms TTL=62
Reply from 10.148.0.171: bytes=32 time=525ms TTL=62
Reply from 10.148.0.171: bytes=32 time=540ms TTL=62
Reply from 10.148.0.171: bytes=32 time=577ms TTL=62
Reply from 10.148.0.171: bytes=32 time=552ms TTL=62
Reply from 10.148.0.171: bytes=32 time=555ms TTL=62
Reply from 10.148.0.171: bytes=32 time=524ms TTL=62
Ping statistics for 10.148.0.171:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 524ms, Maximum = 649ms, Average = 561ms
```

Lista de sites acessados:	
<u>www.globo.com</u> – ok	
<u>www.yahoo.com</u> – ok	
<u>www.hotmail.com</u> – ok	
<u>www.google.com</u> – ok	
www.educacao.mg.gov.br – ok	
<u>www.prodemge.gov.br</u> – ok	
Responsável pelo teste de navegação:	
Nome: Alex Oliver Teixeira	
Função: Coordenador Pedagógico	
Identidade: MG 214828	