

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: João Gustavo F M Sobrinho

GRE/Prodemge: João Antinossi

Responsável/cliente: José Heleno Cardoso de sa

Consórcio Porta kbps Plataforma **VSAT-ID** SEE-MOUL-22538 EMC/Vodanet 2048/1024 **VSAT**



Satellite (DVB) RX Configuration _____ Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 ----

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State

DVB State

: On: Forward link up: 65281, Prodemge@Vodanet

Symbol Rate : 4.883000
S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.6 dB Input Power : -29 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                                          : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
State
                                       : On (DVB-RCS2)
IDU Output Power : -18.4 dBm
ODU Output Power : 35.1 dBm
EIRP
                                          : 48.4 dBW
Es/No
                                            : 15.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -388 us (280785 us)
Frequency correction: -70 Hz
# device show
System Information:
                                                  : SEE-MOUL-22538
        Name
        Location
                                                   : MONTE AZUL - MG
        Contact
                                                   : 0 days, 00:09:13
        System Up time
        CPU Load
                                                    : 16%
                                                   : 08 November 2017 11:09:16
        System time(UTC)
        Broadcast Message : not set
HW:
         Model
                                                    : SatLink 2000
        HW TD
                                                     : 120033
        Main board ID
                                                  : 120026 R6.2
        | : 00:20:0e:10:54:c4 | Satellite (DVB) | : 00:20:0e:10:54:c4 | : 00:20:0e:10:55 | : 00:
MAC addresses:
# arp show
      NetAddr
                                    State
                                                   MacAddr
       10.213.121.2 Dynamic b4:99:ba:00:92:6b
Pinging 10.213.121.1 with 32 bytes of data:
Reply from 10.213.121.1: bytes=32 time=529ms TTL=56
Reply from 10.213.121.1: bytes=32 time=530ms TTL=56
Reply from 10.213.121.1: bytes=32 time=580ms TTL=56
Reply from 10.213.121.1: bytes=32 time=552ms TTL=56
Reply from 10.213.121.1: bytes=32 time=560ms TTL=56
Reply from 10.213.121.1: bytes=32 time=562ms TTL=56
Reply from 10.213.121.1: bytes=32 time=541ms TTL=56
Reply from 10.213.121.1: bytes=32 time=530ms TTL=56
Reply from 10.213.121.1: bytes=32 time=535ms TTL=56
Reply from 10.213.121.1: bytes=32 time=599ms TTL=56
Ping statistics for 10.213.121.1:
       Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
       Minimum = 529ms, Maximum = 599ms, Average = 551ms
```

Lista de sites acessados:
www.globo.com - ok
www.hotmail.com - ok
www.google.com – ok
<u>www.educacao.mg.gov.br</u> – ok
Responsável pelo teste de navegação: Nome: José Heleno Cardoso de sa Função: diretor MASP 859749-4
Telefone: (38) 99839-8126
Horário de funcionamento da escola: 7:00 As 17:20