


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Geralda Veronica da Silva

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-MIAS-22041 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 9/10/2017 21:16:31

Satellite (DVB) RX Configuration _____ : Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176247 GHz : 4.882957 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 14.8 dB SNR Input Power : -34 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -14.3 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.2 dBW
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -194 us (280925 us)
Frequency correction: 130 Hz
System Information:
    Name
                        : SEE-MIAS-22041
    Location
                        : Minas Novas - MG
    Contact
    System Up time : 0 days, 00:40:30 CPU Load : 6%
    System time(UTC) : 09 October 2017 20:20:13
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:57:52
Satellite (DVB) : 00:20:0e:10:57:52
    Ethernet (LAN)
Pinging 10.212.113.1 with 32 bytes of data:
Reply from 10.212.113.1: bytes=32 time=581ms TTL=56
Reply from 10.212.113.1: bytes=32 time=571ms TTL=56
Reply from 10.212.113.1: bytes=32 time=1014ms TTL=56
Reply from 10.212.113.1: bytes=32 time=546ms TTL=56
Reply from 10.212.113.1: bytes=32 time=617ms TTL=56
Reply from 10.212.113.1: bytes=32 time=528ms TTL=56
Reply from 10.212.113.1: bytes=32 time=534ms TTL=56
Reply from 10.212.113.1: bytes=32 time=635ms TTL=56
Reply from 10.212.113.1: bytes=32 time=562ms TTL=56
Reply from 10.212.113.1: bytes=32 time=651ms TTL=56
Ping statistics for 10.212.113.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 528ms, Maximum = 1014ms, Average = 623ms
```

Lista de sites acessados:
www.globo.com – ok www.hotmail.com – ok
www.google.com – ok
<u>www.educacao.mg.gov.br</u> – ok
Responsável pelo teste de navegação: Nome: Geralda Veronica da Silva Função: Vice-Diretora Identidade: MG9175979