

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

GRE/Prodemge: João Antinossi


Consórcio
EMC/Vodanet

Consórcio
SEE-MAPO-23685

SEE-MAPO-23685

Consórcio
SEE-MAPO-23685

Port eth 0 SEE-MAPO-23685 (10.215.46.1)



dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -17.9 dBm

Es/No : 15.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -283 us (266459 us)

Frequency correction: 220 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

```
DVB State
               : Forward link up
               : 65281, Prodemge@Vodanet
Network
Frequency
               : 12.176437 GHz
Symbol Rate
                : 8.882920 Msps
S2 ModCod
   - receiving : 4 QPSK-1/2
   - current max : 22 16APSK-8/9
Pilot
            : On
Frame length
                : Short
                  : ACM
DVB S2 Mode
DVB S2 Stream type: MPEG-TS
Roll off
             : 0.20
SNR
             : 16.4 dB
Input Power
               : -37 dBm
# arp show
             State MacAddr
 NetAddr
  10.215.46.2 Dynamic 1c:39:47:5b:e2:48 1
# device show
System Information:
                : SEE-MAPO-23685
  Name
  Location
                : Matipó - MG
  Contact
  System Up time
                   : 0 days, 00:02:31
                  : 21%
  CPU Load
  System time(UTC) : 09 January 2018 18:01:18
  Broadcast Message : not set
HW:
  Model
                : SatLink 2000
  HW ID
                 : 120033
  Main board ID
                   : 120026 R6.2
MAC addresses:
  Ethernet (LAN)
                   : 00:20:0e:10:7b:72
  Satellite (DVB)
                  : 00:20:0e:10:7b:72
Pinging 10.215.46.1 with 32 bytes of data:
Reply from 10.215.46.1: bytes=32 time=523ms TTL=56
Reply from 10.215.46.1: bytes=32 time=559ms TTL=56
Reply from 10.215.46.1: bytes=32 time=532ms TTL=56
Reply from 10.215.46.1: bytes=32 time=540ms TTL=56
Reply from 10.215.46.1: bytes=32 time=604ms TTL=56
Reply from 10.215.46.1: bytes=32 time=559ms TTL=56
Reply from 10.215.46.1: bytes=32 time=592ms TTL=56
Reply from 10.215.46.1: bytes=32 time=572ms TTL=56
Reply from 10.215.46.1: bytes=32 time=546ms TTL=56
Reply from 10.215.46.1: bytes=32 time=546ms TTL=56
Ping statistics for 10.215.46.1:
  Packets: Sent = 10, Received = 10, Lost = 0 (0\% loss),
Approximate round trip times in milli-seconds:
  Minimum = 523ms, Maximum = 604ms, Average = 557ms
Resp: Maria Conceição
Masp: 832.192-9
Cargo:Diretora
Tel: 031-3873-4042
Horario:07:00-18:00
Onde ficou: na secretaria
www.hotmail.com
www.google.com
www.prodemge.gov.br
```

www.globo.com

www.youtube.com