

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

Operadora/Cliente Ederson Martins


GRE/Prodemge: João Antinossi

Responsável/cliente Eduardo Gomes Silva

Consórcio
EMC/Vodanet

VSAT-ID
SEE-POES-22955
Porta kbps
2Mbps
VSAT

Port eth 0 SEE-POES-22955 (10.215.151.1)



SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -21 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -17.2 dBm
ODU Output Power : 33.2 dBm
EIRP : 46.5 dBW
Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -339 us (280460 us)

Frequency correction: 40 Hz

dvb rx show

```
Satellite (DVB) RX Configuration
```

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Name

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176478 GHz Symbol Rate : 4.882935 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot: On
Frame length: Short
DVB S2 Mode: ACM
DVB S2 Stream type: MPEG-TS

 $\begin{array}{lll} \mbox{Roll off} & : 0.20 \\ \mbox{SNR} & : 15.1 \mbox{ dB} \\ \mbox{Input Power} & : -36 \mbox{ dBm} \\ \end{array}$

arp show

NetAddr State MacAddr If 10.215.151.2 Dynamic 1c:39:47:5b:e2:48 1

device show System Information:

Name : SEE-POES-22955 Location : Ponto dos Voltantes - MG

Contact :

System Up time : 0 days, 00:23:57

CPU Load : 17%

System time(UTC) : 23 November 2017 12:35:45

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:59:0a Satellite (DVB) : 00:20:0e:10:59:0a

Pinging 10.215.151.1 with 32 bytes of data:

Reply from 10.215.151.1: bytes=32 time=543ms TTL=56 Reply from 10.215.151.1: bytes=32 time=553ms TTL=56 Reply from 10.215.151.1: bytes=32 time=580ms TTL=56 Reply from 10.215.151.1: bytes=32 time=581ms TTL=56 Reply from 10.215.151.1: bytes=32 time=945ms TTL=56 Reply from 10.215.151.1: bytes=32 time=945ms TTL=56 Reply from 10.215.151.1: bytes=32 time=598ms TTL=56 Reply from 10.215.151.1: bytes=32 time=540ms TTL=56 Reply from 10.215.151.1: bytes=32 time=521ms TTL=56 Reply from 10.215.151.1: bytes=32 time=519ms TTL=56 Reply from 10.215.151.1: bytes=32 time=519ms TTL=56

Ping statistics for 10.215.151.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds:

Minimum = 519ms, Maximum = 945ms, Average = 593ms

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Eduardo Gomes Silva
Cargo	Diretor
Identidade	1307709-4
Telefone	033-3733-8020
Funcionamento	07:00- 22:00
Onde ficou	No computador da secretaria