


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente : Milton Pereira de Souza

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SACO-222232MbpsVSAT



dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status Rx State : On DVB State : Forward link up Network : 65281, Prodemge@Vodanet Frequency: 12.176616 GHz Symbol Rate : 4.882958 Msps S2 ModCod - receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6 Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS Roll off : 0.20 SNR : 15.8 dB Input Power : -32 dBm # dvb tx show Satellite (DVB) TX Configuration Auto start : Enabled IDU Output Power : -21 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm EIRP : 46.5 dBW

ATM mode : VC-Mux

Default CW Frequency: 0.000000 GHz

Header Compression: UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)

IDU Output Power : -17.7 dBm

ODU Output Power : 32.6 dBm

EIRP : 45.9 dBW

Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -372 us (281625 us)

Frequency correction: 30 Hz

arp show

NetAddr State MacAddr If

10.213.22.2 Dynamic 1c:39:47:5b:e2:48 1

device show

System Information:

Name : SEE-SACO-22223

Location : S O FRANCISCO - MG

Contact :

System Up time : 0 days, 00:18:40

CPU Load : 25%

System time(UTC) : 18 October 2017 12:08:51

Broadcast Message : not set

HW:

Model : SatLink 2000

HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:4d:08

Satellite (DVB) : 00:20:0e:10:4d:08

Pinging 10.213.22.1 with 32 bytes of data:

Reply from 10.213.22.1: bytes=32 time=535ms TTL=56

Reply from 10.213.22.1: bytes=32 time=527ms TTL=56

Reply from 10.213.22.1: bytes=32 time=543ms TTL=56

Reply from 10.213.22.1: bytes=32 time=524ms TTL=56

Reply from 10.213.22.1: bytes=32 time=625ms TTL=56

Reply from 10.213.22.1: bytes=32 time=543ms TTL=56

Reply from 10.213.22.1: bytes=32 time=556ms TTL=56

Reply from 10.213.22.1: bytes=32 time=553ms TTL=56

Reply from 10.213.22.1: bytes=32 time=564ms TTL=56

Reply from 10.213.22.1: bytes=32 time=558ms TTL=56

Ping statistics for 10.213.22.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 524ms, Maximum = 625ms, Average = 552ms

Sites acessados

www.globo.com ok

www.yahoo.com.br- ok

www.hotmail.com- ok

www.google.com - ok

www.prodemge.gov.br - ok

Nome do responsável: Milton Pereira de Souza

RG: 1569447 Cargo: Diretor