

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gustavo de Oliveira

GRE/Prodemge: João Antinossi Responsável/cliente: Daniela Rodrigues da Silva

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-IPBA-23155 2Mbps

Port eth0 on SEE-IPBA-23155 (10.214.153.1)



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65261, ... : 12.176741 GHz : 4.883051 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.8 dB Input Power : -33 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -22.7 dBm
ODU Output Power : 32.8 dBm
EIRP
                     : 46.1 dBW
Es/No
                     : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -371 us (281393 us)
Frequency correction: 20 Hz
System Information:
    Name
                        : SEE-IPBA-23155
    Location
                         : IPABA - MG
    Contact
    System Up time : 0 days, 00:24:21

CPU Load : 13%

System time(UTC) : 07 December 2017 13:05:03
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:54:51
Satellite (DVB) : 00:20:0e:10:54:51
    Ethernet (LAN)
NetAddr
           State MacAddr
   10.214.153.2 Dynamic 64:1c:67:61:83:29 1
Pinging 10.214.153.1 with 32 bytes of data:
Reply from 10.214.153.1: bytes=32 time=543ms TTL=56
Reply from 10.214.153.1: bytes=32 time=584ms TTL=56
Reply from 10.214.153.1: bytes=32 time=553ms TTL=56
Reply from 10.214.153.1: bytes=32 time=559ms TTL=56
Reply from 10.214.153.1: bytes=32 time=562ms TTL=56
Reply from 10.214.153.1: bytes=32 time=581ms TTL=56
Reply from 10.214.153.1: bytes=32 time=539ms TTL=56
Reply from 10.214.153.1: bytes=32 time=560ms TTL=56
Reply from 10.214.153.1: bytes=32 time=583ms TTL=56
Reply from 10.214.153.1: bytes=32 time=676ms TTL=56
Ping statistics for 10.214.153.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 539ms, Maximum = 676ms, Average = 574ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Daniela Rodrigues da Silva Função: Diretora MASP: 1007724-6 Telefone: 33-991563301 Funcionamento: 07:00h às 22:00h