



TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE				
NOC/Operadora: Ermínio Junior		Operadora/Cliente João Gustavo		
GRE/Prodemge: João Antinossi		Responsável/cliente Ru	ıth Costa Simões	
Consórcio EMC/Vodanet	VSAT-ID SEE-SAAS-22791	Porta kbps 2Mbps	Plataforma VSAT	





SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -20.0 dBm

Es/No : 11.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -363 us (280654 us)

Frequency correction: 60 Hz

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176498 GHz Symbol Rate : 4.882945 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 15.5 dB Input Power : -40 dBm

"

arp sh# ow

NetAddr State MacAddr If

10.214.105.2 Dynamic b4:99:ba:00:92:6b 1

device show

System Information:

Name : SEE-SAAS-22791 Location : SALINAS - MG

Contact :

System Up time : 0 days, 00:58:49

CPU Load : 17%

System time(UTC) : 17 November 2017 12:33:38

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:58:a5 Satellite (DVB) : 00:20:0e:10:58:a5

Pinging 10.214.105.1 with 32 bytes of data:

```
Reply from 10.214.105.1: bytes=32 time=531ms TTL=56 Reply from 10.214.105.1: bytes=32 time=532ms TTL=56 Reply from 10.214.105.1: bytes=32 time=570ms TTL=56 Reply from 10.214.105.1: bytes=32 time=522ms TTL=56 Reply from 10.214.105.1: bytes=32 time=537ms TTL=56 Reply from 10.214.105.1: bytes=32 time=548ms TTL=56 Reply from 10.214.105.1: bytes=32 time=558ms TTL=56 Reply from 10.214.105.1: bytes=32 time=545ms TTL=56 Reply from 10.214.105.1: bytes=32 time=655ms TTL=56 Reply from 10.214.105.1: bytes=32 time=655ms TTL=56 Reply from 10.214.105.1: bytes=32 time=573ms TTL=56
```

Ping statistics for 10.214.105.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 522ms, Maximum = 655ms, Average = 557ms www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Ruth Costa Simões	
Cargo	Diretora	
Identidade	351500-4	
Telefone	038-9-9119-3791	
Funcionamento	07:00-17:15	
Onde ficou	Conectado ao um computador da	
	diretoria	