


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Sergio Almeida

GRE/Prodemge: João Antinossi Responsável/cliente: Alfredo Luciano

> Porta kbps Consórcio **VSAT-ID Plataforma** EMC/Vodanet SEE-JUTO-23705 2Mbps **VSAT**



Satellite (DVB) RX Configuration _____ Auto start

: Enabled Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

8.883000 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

12.176420 DVB-S2 2 0 0.0 E 1 1 4.883300

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network

: Forward link up : 65281, Prodemge@Vodanet : 12.176490 GHz Frequency Symbol Rate : 8.882841 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

: On Pilot Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.9 dB SNR : -31 dBm Input Power

```
Satellite (DVB) TX Configuration
 Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-I
IDU Output Power : -18.3 dBm
ODU Output Power : 32.7 dBm
State
                    : On (DVB-RCS2)
EIRP
                     : 46.0 dBW
Es/No
                     : 15.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -289 us (266154 us)
Frequency correction: 90 Hz
System Information:
    Name
                        : SEE-JUTO-23705
    Location
                         : Juramento - MG
    Contact
    System Up time : 0 days, 00:33:01

CPU Load : 20%

System time(UTC) : 10 January 2018 19:42:35
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5f:18
Satellite (DVB) : 00:20:0e:10:5f:18
NetAddr
             State MacAddr
                                           Ιf
10.213.219.2 Dynamic 74:e6:e2:d4:e4:73 1
Pinging 10.213.219.1 with 32 bytes of data:
Reply from 10.213.219.1: bytes=32 time=544ms TTL=56
Reply from 10.213.219.1: bytes=32 time=558ms TTL=56
Reply from 10.213.219.1: bytes=32 time=528ms TTL=56
Reply from 10.213.219.1: bytes=32 time=520ms TTL=56
Reply from 10.213.219.1: bytes=32 time=558ms TTL=56
Reply from 10.213.219.1: bytes=32 time=533ms TTL=56
Reply from 10.213.219.1: bytes=32 time=520ms TTL=56
Reply from 10.213.219.1: bytes=32 time=565ms TTL=56
Reply from 10.213.219.1: bytes=32 time=544ms TTL=56
Reply from 10.213.219.1: bytes=32 time=540ms TTL=56
Ping statistics for 10.213.219.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 520ms, Maximum = 565ms, Average = 541ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável : Alfredo Luciano
Cargo: ATB (Auxiliar. Secretaria)
MASP: 12169033
Telefone: 38 3421-0531
Funcionamento: 07:00h às 18:00h