


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Gilvan P de Brito Júnior

Responsável/cliente: Mirreyle Mendes Cunha **GRE/Prodemge:** João Antinossi

> Consórcio VSAT-ID Plataforma Porta kbps EMC/Vodanet SEE-JABA-22528 2048/1024 **VSAT**



Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E \* 0 0

Yes

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

Frequency : 12.176295 GHz Symbol Rate : 4.882985 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.5 dB Input Power : -34 dBm

```
Satellite (DVB) TX Configuration
 ______
                   : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -12.7 dBm
ODU Output Power : 34.9 dBm
EIRP
                    : 48.2 dBW
Es/No
                    : 16.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -258 us (281134 us)
Frequency correction: 150 Hz
System Information:
   Name
                       : SEE-JABA-22528
    Location
                       : JA BA - MG
    Contact
   System Up time : 0 days, 00:35:10 CPU Load : 9%
    System time(UTC) : 04 November 2017 19:11:47
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
                       : 120026 R6.2
    Main board ID
    MAC addresses:
Pinging 10.213.111.1 with 32 bytes of data:
Reply from 10.213.111.1: bytes=32 time=580ms TTL=56
Reply from 10.213.111.1: bytes=32 time=609ms TTL=56
Reply from 10.213.111.1: bytes=32 time=547ms TTL=56
Reply from 10.213.111.1: bytes=32 time=580ms TTL=56
Reply from 10.213.111.1: bytes=32 time=539ms TTL=56
Reply from 10.213.111.1: bytes=32 time=559ms TTL=56
Reply from 10.213.111.1: bytes=32 time=582ms TTL=56
Reply from 10.213.111.1: bytes=32 time=539ms TTL=56
Reply from 10.213.111.1: bytes=32 time=579ms TTL=56
Reply from 10.213.111.1: bytes=32 time=559ms TTL=56
Ping statistics for 10.213.111.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 539ms, Maximum = 609ms, Average = 567ms
NetAddr
          State MacAddr
   10.213.111.2 Dynamic e8:9a:8f:b7:bd:4a
```

## Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br – ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Mirreyle Mendes Cunha Função: VICE-Diretora Telefone: 38 -9 9131-5100 MASP: 852097-5 Horário: 7:00 as 17:20