


# TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE			
NOC/Operadora: Ermínio Junior		Operadora/Cliente Gilvan Junior	
GRE/Prodemge: João Antinossi		Responsável/cliente Va	anda Rodrigues Gomes
Consórcio EMC/Vodanet	VSAT-ID SEE-GOES-22808	Porta kbps 2Mbps	<b>Plataforma</b> VSAT





## SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57 # dvb tx show

## Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -21 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 35.2 dBm EIRP : 48.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

#### Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -12.3 dBm
ODU Output Power : 34.9 dBm
EIRP : 48.2 dBW
Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -266 us (281106 us)

Frequency correction: 90 Hz

# dvb rx show

### Satellite (DVB) RX Configuration

-----

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Name

#### Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176173 GHz Symbol Rate : 4.883015 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

 $\begin{array}{lll} \mbox{Roll off} & : 0.20 \\ \mbox{SNR} & : 16.3 \mbox{ dB} \\ \mbox{Input Power} & : -30 \mbox{ dBm} \end{array}$ 

# ar'p show No Such Command # arp show

> NetAddr State MacAddr If 10.214.222.2 Dynamic e8:9a:8f:b7:bd:4a 1

# device show System Information:

Name : SEE-GOES-22808

Location : GOVERNADOR VALADARES

Contact :

System Up time : 2 days, 20:31:51

CPU Load : 16%

System time(UTC) : 17 November 2017 16:31:19

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:51:d1 Satellite (DVB) : 00:20:0e:10:51:d1

#

Pinging 10.214.222.1 with 32 bytes of data:

Reply from 10.214.222.1: bytes=32 time=547ms TTL=56 Reply from 10.214.222.1: bytes=32 time=548ms TTL=56 Reply from 10.214.222.1: bytes=32 time=553ms TTL=56 Reply from 10.214.222.1: bytes=32 time=543ms TTL=56 Reply from 10.214.222.1: bytes=32 time=539ms TTL=56 Reply from 10.214.222.1: bytes=32 time=601ms TTL=56 Reply from 10.214.222.1: bytes=32 time=515ms TTL=56 Reply from 10.214.222.1: bytes=32 time=536ms TTL=56 Reply from 10.214.222.1: bytes=32 time=542ms TTL=56 Reply from 10.214.222.1: bytes=32 time=542ms TTL=56 Reply from 10.214.222.1: bytes=32 time=561ms TTL=56

Ping statistics for 10.214.222.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 515ms, Maximum = 601ms, Average = 548ms

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Vanda Rodrigues Gomes
Cargo	Diretora
Identidade	894067-8
Telefone	033-4042-1827
Funcionamento	07:00-16:30
Onde ficou	Diretoria