

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Rodrigo Alves

Responsável/cliente: Marli Maria Rodrigues GRE/Prodemge: João Antinossi

Batista

Consórcio VSAT-ID Porta kbps Plataforma EMC/Vodanet SEE-MOOS-22741 2048/1024 **VSAT**



Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State

DVB State

On Forward link up : 65281, Prodemge@Vodanet Network

: 65281, Proder : 12.176154 GHz : 4 882000 Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.7 dB Input Power : -41 dBm

```
Satellite (DVB) TX Configuration
 _____
                     : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                     : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                     : On (DVB-RCS2)
State
IDU Output Power : -7.2 dBm
ODU Output Power : 32.8 dBm
EIRP
                      : 46.1 dBW
Es/No
                      : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -363 us (281414 us)
Frequency correction: 140 Hz
System Information:
                      : SEE-MOOS-22741
   Name
    Location
                      : MONTES CLAROS - MG
    Contact
    System Up time : 0 days, 00:04:13
    CPU Load
                       : 9%
    System time(UTC) : 17 November 2017 15:24:25
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
                        : 120033
    HW TD
    Main board ID
                       : 120026 R6.1
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:48:9f
Satellite (DVB) : 00:20:0e:10:48:9f
# arp show
   NetAddr
                State
                       MacAddr
   10.213.252.2 Dynamic 74:e6:e2:d4:e4:73
Pinging 10.213.252.1 with 32 bytes of data:
Reply from 10.213.252.1: bytes=32 time=567ms TTL=56
Reply from 10.213.252.1: bytes=32 time=579ms TTL=56
Reply from 10.213.252.1: bytes=32 time=537ms TTL=56
Reply from 10.213.252.1: bytes=32 time=564ms TTL=56
Reply from 10.213.252.1: bytes=32 time=533ms TTL=56
Reply from 10.213.252.1: bytes=32 time=583ms TTL=56
Reply from 10.213.252.1: bytes=32 time=563ms TTL=56
Reply from 10.213.252.1: bytes=32 time=519ms TTL=56
Reply from 10.213.252.1: \overline{\text{bytes}}=32 time=556ms TTL=56
Reply from 10.213.252.1: bytes=32 time=559ms TTL=56
Ping statistics for 10.213.252.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 519ms, Maximum = 583ms, Average = 556ms
```

Lista de sites acessados:	
www.globo.com – ok	
www.hotmail.com – ok	
<u>www.google.com</u> – ok <u>www.educacao.mg.gov.br</u> – ok	
Responsável pelo teste de navegação: Nome: Marli Maria Rodrigues Batista Função: Diretora MASP 3317104 Telefone: (38) 3214-1894 Horário de funcionamento da escola: 07:00 as 17:00	