



TERMO DE ACEITE TÉCNICO





dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -18.8 dBm
ODU Output Power : 32.9 dBm

EIRP : 46.2 dBW Es/No : 10.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -428 us (281415 us)

Frequency correction: 40 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176237 GHz Symbol Rate : 4.883016 Msps

S2 ModCod

- receiving : 4 QPSK-1/2

- current max : 21 16APSK-5/6

Pilot : On Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 16.5 dB Input Power : -35 dBm

arp show

NetAddr State MacAddr If 10.212.47.2 Dynamic 80:ee:73:a4:e2:ba 1

device show

System Information:

Name : SEE-JAIA-21959 Location : JANUARIA

Contact :

System Up time : 0 days, 00:25:07

CPU Load : 13%

System time(UTC) : 24 October 2017 12:45:13

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:52:10 Satellite (DVB) : 00:20:0e:10:52:10

Pinging 10.212.47.1 with 32 bytes of data:

```
Reply from 10.212.47.1: bytes=32 time=501ms TTL=56 Reply from 10.212.47.1: bytes=32 time=569ms TTL=56 Reply from 10.212.47.1: bytes=32 time=562ms TTL=56 Reply from 10.212.47.1: bytes=32 time=567ms TTL=56 Reply from 10.212.47.1: bytes=32 time=528ms TTL=56 Reply from 10.212.47.1: bytes=32 time=539ms TTL=56 Reply from 10.212.47.1: bytes=32 time=539ms TTL=56 Reply from 10.212.47.1: bytes=32 time=547ms TTL=56 Reply from 10.212.47.1: bytes=32 time=539ms TTL=56 Reply from 10.212.47.1: bytes=32 time=539ms TTL=56 Reply from 10.212.47.1: bytes=32 time=530ms TTL=56
```

Ping statistics for 10.212.47.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 501ms, Maximum = 559ms, Average = 514ms

#

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Francisca Lima Pimenta
Cargo	Diretora
Identidade	595597-6
Telefone	****