

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Gustavo Henrique Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Luciano Carlos De Lemos

> Porta kbps Plataforma Consórcio **VSAT-ID** SEE-MAIM-23680 EMC/Vodanet 2Mbps **VSAT**

Port eth0 on SEE-JOIA-23122 (10.214.37.1)



dvb rx show

Satellite (DVB) RX Configuration : Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E Yes

1 0 0.0 E 12.176420 DVB-S2 2 4.883300 1

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

: Forward link up

: 65281, Prodemge@Vodanet

: Forward link : 65281, Proder : 12.176430 GHz Symbol Rate : 8.883025 : 8.883025

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On : Short Frame length <u>:</u> ACM DVB S2 Mode

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                    : 16.6 dB
SNR
Input Power
                    : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start
Auto start : Enabled IDU Output Power : -18 dBm
                    : Enabled
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -17.9 dBm

Es/No : 16.5
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -344 us (266295 us)
Frequency correction: -10 Hz
# device show
System Information:
   Name
                        : SEE-MAIM-23680
    Location
                        : Manhumirim - MG
    Contact
    System Up time : 0 days, 00:17:22

CPU Load : 27%

System time(UTC) : 15 January 2018 12:22:10
    Broadcast Message : not set
HW:
    HW ID
                        : SatLink 2000
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:7b:27
Satellite (DVB) : 00:20:0e:10:7b:27
Pinging 10.215.41.1 with 32 bytes of data:
Reply from 10.215.41.1: bytes=32 time=553ms TTL=56
Reply from 10.215.41.1: bytes=32 time=546ms TTL=56
Reply from 10.215.41.1: bytes=32 time=622ms TTL=56
Reply from 10.215.41.1: bytes=32 time=535ms TTL=56
Reply from 10.215.41.1: bytes=32 time=539ms TTL=56
Reply from 10.215.41.1: bytes=32 time=559ms TTL=56
Reply from 10.215.41.1: bytes=32 time=532ms TTL=56
Reply from 10.215.41.1: bytes=32 time=519ms TTL=56
Reply from 10.215.41.1: bytes=32 time=539ms TTL=56
Reply from 10.215.41.1: bytes=32 time=516ms TTL=56
Lista de sites acessados:
www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok
```

www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Responsável pelo teste de navegação: NomeLuciano Carlos De Lemos
Função: Diretor
MASP: 666.703-4