



dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm

ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -13.8 dBm
ODU Output Power : 32.5 dBm

EIRP : 45.8 dBW Es/No : 14.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -419 us (281075 us)

Frequency correction: 60 Hz

dvb rx show

Satellite (DVB) RX Configuration

_____ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Enable Name

4.883300 12.176420 DVB-S2 104 $0 \ 0.0 \, \mathrm{E}$ Yes 1 1 16.667000 0.0EYes 11.962753 DVB-S2 2

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up
Network : 65281, Prodemge@Vodanet

Frequency : 12.176091 GHz Symbol Rate : 4.882936 Msps

S2 ModCod

- receiving : 4 QPSK-1/2

- current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS Roll off : 0.20

SNR : 15.8 dB Input Power : -36 dBm

arp show

NetAddr State MacAddr If 10.212.235.2 Dynamic b4:99:ba:00:92:6b 1

device show

System Information:

Name : SEE-MIIA-22182 : Mirav nia - MG Location

Contact

System Up time : 0 days, 00:22:10

: 15% CPU Load

System time(UTC) : 26 October 2017 17:20:57

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.1

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:49:fb Satellite (DVB) : 00:20:0e:10:49:fb

Pinging 10.212.235.1 with 32 bytes of data:

```
Reply from 10.212.235.1: bytes=32 time=556ms TTL=56 Reply from 10.212.235.1: bytes=32 time=545ms TTL=56 Reply from 10.212.235.1: bytes=32 time=580ms TTL=56 Reply from 10.212.235.1: bytes=32 time=537ms TTL=56 Reply from 10.212.235.1: bytes=32 time=561ms TTL=56 Reply from 10.212.235.1: bytes=32 time=577ms TTL=56 Reply from 10.212.235.1: bytes=32 time=541ms TTL=56 Reply from 10.212.235.1: bytes=32 time=524ms TTL=56 Reply from 10.212.235.1: bytes=32 time=519ms TTL=56 Reply from 10.212.235.1: bytes=32 time=519ms TTL=56 Reply from 10.212.235.1: bytes=32 time=550ms TTL=56
```

Ping statistics for 10.212.235.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 519ms, Maximum = 580ms, Average = 549ms

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Wilson Ribeiro
Cargo	Diretor
Identidade	11519675
Telefone	038-9-9735-5281
Funcionamento	07:00 até 11:20