


TERMO DE ACEITE TÉCNICO

Name

Solicitante: PRODEMGE / SEE			
NOC/Operadora: Ermínio Junior		Operadora/Cliente Eduardo Tarda	
GRE/Prodemge: João Antinossi		Responsável/cliente Mary dos Santos Pereira	
Consórcio EMC/Vodanet	VSAT-ID SEE-FRAR-22818	Porta kbps 2Mbps	Plataforma VSAT





SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176674 GHz Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS Roll off : 0.20 SNR : 15.6 dB : -36 dBm Input Power # dvb tx show Satellite (DVB) TX Configuration Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm EIRP : 46.5 dBW Default CW Frequency: 0.000000 GHz ATM mode : VC-Mux Header Compression: UDP/IP Satellite (DVB) Transmitter Status : On (DVB-RCS2) State IDU Output Power : -20.6 dBm ODU Output Power : 33.3 dBm **EIRP** : 46.6 dBW Es/No : 13.5 dB Header Compression: Disabled - HC for RCS2 not supported by HUB Timing correction: -452 us (281581 us) Frequency correction: 40 Hz # arp show State MacAddr NetAddr 10.215.111.2 Dynamic b8:70:f4:6e:b3:ab 1 # device show System Information: : SEE-FRAR-22818 Name Location : Frei Gaspar - MG Contact System Up time : 0 days, 01:31:30 : 15% CPU Load System time(UTC) : 13 November 2017 20:04:45 Broadcast Message : not set HW: Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.2 MAC addresses: Ethernet (LAN) : 00:20:0e:10:4f:5d Satellite (DVB) : 00:20:0e:10:4f:5d Pinging 10.215.111.1 with 32 bytes of data: Reply from 10.215.111.1: bytes=32 time=570ms TTL=56 Reply from 10.215.111.1: bytes=32 time=535ms TTL=56 Reply from 10.215.111.1: bytes=32 time=523ms TTL=56 Reply from 10.215.111.1: bytes=32 time=562ms TTL=56 Reply from 10.215.111.1: bytes=32 time=555ms TTL=56 Reply from 10.215.111.1: bytes=32 time=558ms TTL=56

Reply from 10.215.111.1: bytes=32 time=579ms TTL=56 Reply from 10.215.111.1: bytes=32 time=566ms TTL=56 Reply from 10.215.111.1: bytes=32 time=559ms TTL=56 Reply from 10.215.111.1: bytes=32 time=532ms TTL=56

Ping statistics for 10.215.111.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds: Minimum = 523ms, Maximum = 579ms, Average = 513ms

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Mary dos Santos Pereira
Cargo	Diretora
Identidade	636469-9
Telefone	033-3512-1131
Funcionamento	07:00-22:00