

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente Ivan Ribeiro

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-RIAS-225542MbpsVSAT

Port eth 0 on SEE-RIAS-22554 (10.213.137.1)



dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176505 GHz Symbol Rate : 4.882955 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6 Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 15.8 dB Input Power : -32 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm

ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -18.3 dBm
ODU Output Power : 33.1 dBm

EIRP : 46.4 dBW Es/No : 12.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -201 us (280561 us)

Frequency correction: 120 Hz

arp show

NetAddr State MacAddr If

10.213.137.2 Dynamic 80:ee:73:a4:e2:ba 1

device show

System Information:

Name : SEE-RIAS-22554

Location : Rio Pardo de Minas - MG

Contact :

System Up time : 0 days, 00:08:28

CPU Load : 8%

System time(UTC) : 11 November 2017 20:29:34

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:5b:87 Satellite (DVB) : 00:20:0e:10:5b:87 Pinging 10.213.137.1 with 32 bytes of data: Reply from 10.213.137.1: bytes=32 time=574ms TTL=56 Reply from 10.213.137.1: bytes=32 time=575ms TTL=56 Reply from 10.213.137.1: bytes=32 time=582ms TTL=56 Reply from 10.213.137.1: bytes=32 time=572ms TTL=56 Reply from 10.213.137.1: bytes=32 time=557ms TTL=56 Reply from 10.213.137.1: bytes=32 time=519ms TTL=56 Reply from 10.213.137.1: bytes=32 time=536ms TTL=56 Reply from 10.213.137.1: bytes=32 time=519ms TTL=56 Reply from 10.213.137.1: bytes=32 time=568ms TTL=56 Reply from 10.213.137.1: bytes=32 time=573ms TTL=56 Ping statistics for 10.213.137.1: Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 519 ms, Maximum = 582ms, Average = 510ms Lista de sites acessados: www.globo.com - ok www.hotmail.com - ok

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok

Responsável pelo teste de navegação:

Nome: Ivan Ribeiro Função: Secretario Identidade: 132098-7 Telefone: 038-9-9124-1342 Horario: 06:00 às 12:00