


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Erica Mendes de Matos Rocha

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SACO-222132MbpsVSAT



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176422 GHz Symbol Rate : 4.882893 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20

SNR : 15.9 dB

Input Power : -27 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.3 dBm
ODU Output Power : 32.5 dBm
EIRP
                    : 45.8 dBW
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -441 us (281576 us)
Frequency correction: 20 Hz
System Information:
                    : SEE-SACO-22213
    Name
    Location
                        : SÃO FRANCISCO - MG
    Contact
    System Up time : 0 days, 00:12:54 CPU Load : 15%
    System time (UTC) : 31 October 2017 11:29:49
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:57:e4
Satellite (DVB) : 00:20:0e:10:57:e4
NetAddr
           State MacAddr
    10.213.12.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.12.1 with 32 bytes of data:
Reply from 10.213.12.1: bytes=32 time=542ms TTL=56
Reply from 10.213.12.1: bytes=32 time=542ms TTL=56
Reply from 10.213.12.1: bytes=32 time=532ms TTL=56
Reply from 10.213.12.1: bytes=32 time=529ms TTL=56
Reply from 10.213.12.1: bytes=32 time=565ms TTL=56
Reply from 10.213.12.1: bytes=32 time=547ms TTL=56
Reply from 10.213.12.1: bytes=32 time=520ms TTL=56
Reply from 10.213.12.1: bytes=32 time=565ms TTL=56
Reply from 10.213.12.1: bytes=32 time=566ms TTL=56
Reply from 10.213.12.1: bytes=32 time=560ms TTL=56
Ping statistics for 10.213.12.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 520ms, Maximum = 566ms, Average = 546ms
```

Lista de sites acessados:
www.globo.com - ok www.hotmail.com - ok www.google.com - ok
www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: Erica Mendes de Matos Rocha Função: Diretora Identidade: MASP 59559580
Telefone: 38-99967-7612
Horário de funcionamento – 07hrs às 18hrs