



dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -13.8 dBm
ODU Output Power : 32.5 dBm

EIRP : 45.8 dBW Es/No : 14.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -419 us (281075 us)

Frequency correction: 60 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 $0 \ 0.0 \, \mathrm{E}$ Yes 1 1 16.667000 11.962753 DVB-S2 2 0.0EYes

Satellite (DVB) Receiver Status

DVB State Rx State : On

: Forward link up

: 65281, Prodemge@Vodanet

Network : 65281, Prodemg Frequency : 12.176091 GHz Symbol Rate : 4.882936 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On

: Short Frame length DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 15.8 dB Input Power : -36 dBm

arp show

State MacAddr NetAddr If 10.213.69.2 Dynamic 74:e6:e2:d4:e4:73 1

device show

System Information:

: SEE-SAES-22270 Name

: So Jo das Misses - MG Location

Contact

System Up time : 0 days, 00:08:52

CPU Load : 15%

System time(UTC) : 30 October 2017 18:56:49

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:53:58 Satellite (DVB) : 00:20:0e:10:53:58

Pinging 10.213.69.1 with 32 bytes of data:

Reply from 10.213.69.1: bytes=32 time=554ms TTL=56 Reply from 10.213.69.1: bytes=32 time=565ms TTL=56 Reply from 10.213.69.1: bytes=32 time=567ms TTL=56 Reply from 10.213.69.1: bytes=32 time=569ms TTL=56 Reply from 10.213.69.1: bytes=32 time=526ms TTL=56 Reply from 10.213.69.1: bytes=32 time=571ms TTL=56 Reply from 10.213.69.1: bytes=32 time=579ms TTL=56 Reply from 10.213.69.1: bytes=32 time=558ms TTL=56 Reply from 10.213.69.1: bytes=32 time=533ms TTL=56 Reply from 10.213.69.1: bytes=32 time=575ms TTL=56 Reply from 10.213.69.1: bytes=32 time=575ms TTL=56

Ping statistics for 10.213.69.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 526ms, Maximum = 579ms, Average = 559ms

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Iverina Ferreira
Cargo	Diretora
Identidade	10080232
Telefone	038-9-9814-9668
Funcionamento	****