

# **TERMO DE ACEITE TÉCNICO**

Solicitante: VIVO- Projeto Escolas Rurais

NOC/Operador: Rogério Momi Frias Cliente: VIVO

 Empresa
 VSAT-ID
 Link kbps
 Plataforma

 EMC Brasil
 VIVO-PER-28023366-SE
 256/128
 VSAT



### Satellite (DVB) RX Configuration

Auto start : Enabled

Max Signalling MODCOD: 23 16APSK-9/10 Max Traffic MODCOD: 28 32APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

\* 0 0 9.320000 12.055825 DVB-S2 102 0 0.0 E Yes

#### Satellite (DVB) Receiver Status

D. Otata . Oa

Rx State : On

DVB State : Forward link up Network : 1326, T14R Beam Frequency : 12.055914 GHz Symbol Rate : 9.319986 Msps

S2 ModCod

- receiving : 15 8PSK-5/6 - current max : 16 8PSK-8/9

Pilot : On
Frame length : Short
DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 15.0 dB Input Power : -36 dBm

## Satellite (DVB) TX Configuration

Auto start : Enabled
BUPC status : Disabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : None

#### Satellite (DVB) Transmitter Status

-----

State : On (DVB-RCS) IDU Output Power : -19.8 dBm

Es/No : 12.5 dB

Header Compression: Disabled

Timing correction: -182 us (262044 us)

Frequency correction: 10 Hz

```
Resporta de 8.8.8.8: bytes=32 tenpo=669ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=769ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=720ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=639ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=639ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=666ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=661ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=660ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=660ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=670ms IIL=43
Resporta de 8.8.8.8: bytes=32 tenpo=6
```